



OPEL Corsa Corsa 1.4 16V

VIN NO W0L0SDL08B6097271

Registration Number 08B6097271



MOT Date

2026-03-01

Last Service

2025-04-15

Number of Owners

2

Last Service Mileage

93007

Number of Keys

2

First Registration Date

2011-05-12

Odometer Reading

94778 km

Country First Registered

-

Inspection Report Summary

Customer	BCA Online	Report Number	P20250812090050
Inspection Date / Place	2025-08-12 / BCA Berlin	Cosmetic Grade	5


Vehicle Summary

Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Petrol	Road Worthy	Unknown
Colour	Black	Engine Size (cc)	1398
Engine Size	1.4	No of Doors	3
Body Type	Sedan	Drive Train	Front
Seat Colour		No of Seats	5
Seat Covering Name		Seat Covering	Cloth
Charging Cables		NEDC CO2 Rating (q/km)	134
Gearbox Type	Manual		

Vehicle History & Documents

Service Book Available	Present	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warrenty			







Equipment

Tinted Glass	Anti-lock braking	Heated wing mirrors	Remote central locking
CD Player	Rear parking sensors	Airbag Status	Front fog lamps
Remote adjusting wing mirrors	Stability control	Radio	

Equipment Details


Air Conditioning	Yes	Seat Heating	Front
------------------	-----	--------------	-------

Wheels & Tyres


Right Front Tyre Depth	6	Left Front Tyre Depth	6
Right Rear Tyre Depth	7	Left Rear Tyre Depth	7

Cosmetic Damage

15 Schäden



2 Schäden




Component		Damage	Comments
1	Fender / Front Left	Paint / Scratch / Scuff	
2	Mirror Shell / Front Left	Paint / Scratch / Scuff	
3	Door / Front Left	Paint / Scratch / Scuff	
4	Side Panel / Back Left	Paint / Scratch / Scuff	
5	Side Panel / Back Left	Paint / Scratch / Scuff	
6	Bumper / Back	Bodywork / Breakage	
7	Bumper / Back	Paint / Scratch / Scuff	
8	Bumper / Back	Paint / Scratch / Scuff	
9	Tailgate light	Paint / Scratch / Scuff	
10	Bumper / Back	Paint / Scratch / Scuff	
11	Door / Back Right	Paint / Scratch / Scuff	
12	Door / Front Right	Paint / Scratch / Scuff	

13	Door / Front Right	Bodywork / Dent / Dent
14	Fender / Front Right	Paint / Scratch / Scuff
15	Hood	Bodywork / Dent / Dent
16	Center Console	Interior / Dirty
17	Center Console	Interior / Dirty



1. Fender / Front Left
Paint / Scratch / Scuff -



2. Mirror Shell / Front Left
Paint / Scratch / Scuff -



3. Door / Front Left
Paint / Scratch / Scuff -



4. Side Panel / Back Left
Paint / Scratch / Scuff -



5. Side Panel / Back Left
Paint / Scratch / Scuff -




6. Bumper / Back
Bodywork / Breakage -




7. Bumper / Back
Paint / Scratch / Scuff -



8. Bumper / Back
Paint / Scratch / Scuff -



9. Tailgate light
Paint / Scratch / Scuff -




10. Bumper / Back
Paint / Scratch / Scuff -



11. Door / Back Right
Paint / Scratch / Scuff -




12. Door / Front Right
Paint / Scratch / Scuff -




13. Door / Front Right
Bodywork / Dent / Dent -



14. Fender / Front Right
Paint / Scratch / Scuff -



15. Hood
Bodywork / Dent / Dent -



16. Center Console
Interior / Dirty -



17. Center Console
Interior / Dirty -

Mechanical Condition

Engine

Engine Starts	✓	Engine Status / EML	✓
Engine Leak Visible	✓		

Control Lights

ABS Warning Light	✓	ESP Fault/Traction Control Malfunction Light	✓
Airbag Warning Light	✓	Oil Pressure Warning Light	✓
Brake Warning Light	✓	Power Steering Warning Light	✓
Alternator / Battery	✓	No Dashboard Lights	✓
Display Defect	✓	Tire Pressure Monitoring System	✓

Gearbox

Gear Box	✓
----------	---

Equipments Test

Other Equipments	✓	Main & Spare Keys Functioning	✓
Electric Windows	✓	Audio Equipment	✓
Parking Sensors / Cameras Functioning	✓	AC / Heating System	✓
Central Locking	✓		

Levels

Brakes Fluid	✓	Coolant Fluid	✓
--------------	---	---------------	---

Test Drive Inspection

Engine			
Engine Noise	✓	Fume Quantity	✓
Power Loss	✓	The Gears Scratch / Skip / Abnormal Operation	✓
Brake			
Brake System Anomaly	✓		
Clutch			
Clutch Pedal Low / High	✓	Clutch Abnormal	✓
Clutch Functioning	✓		
Steering Wheel			
Flywheel Noise	✓	Steering Noise / Anomaly	✓
General			
Test Driven Status	✓		
✓ <i>No troubles detected, good condition or correct tests, according to vehicle age and mileage</i>			
! <i>Damages or malfunction detected that requires repairs by the buyer</i>			
NA <i>Not applicable</i>			
☐ <i>Not tested</i>			

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description. [User Guide](#)