



OPEL Corsa Corsa 1.4 16V

VIN NO W0L0SDL08B6109908

Registration Number 08B6109908



MOT Date



Last Service

2024-03-26

Number of Owners



Last Service Mileage

139355

Number of Keys



First Registration Date

2011-06-30

Odometer Reading



148348 km

Country First Registered



Inspection Report Summary

Customer	BCA Online	Report Number	P20250902140821
Inspection Date / Place	2025-09-02 / Dürkop Braunschweig Nord	Cosmetic Grade	1

Vehicle Summary

Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Petrol	Road Worthy	Yes
Colour	Black	Engine Size (cc)	1398
Engine Size	1.4	No of Doors	3
Body Type	Sedan	Drive Train	Front
Seat Colour		No of Seats	5
Seat Covering Name		Seat Covering	Cloth
Charging Cables		NEDC CO2 Rating (q/km)	134
Gearbox Type	Manual		

Vehicle History & Documents

Service Book Available	Present	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warrenty			







Equipment

Airbag Status	Anti-lock braking	Front fog lamps	Remote adjusting wing mirrors
Stability control	Central locking	Radio	Rear parking sensors
Alloys wheels	Enhanced speaker system	Heated wing mirrors	Sports seats
CD Player	Leather steering wheel	Rain sensitive windscreen wipers	

Equipment Details


Air Conditioning	Yes	Alloy Wheel Size	17
Seat Heating	Front		

Wheels & Tyres


Right Front Tyre Depth	5	Left Front Tyre Depth	5
Right Rear Tyre Depth	5	Left Rear Tyre Depth	4

Cosmetic Damage

5 Schäden



0 Schäden



Component		Damage	Comments
1	Rim / Back Left	Out of Bodywork / Scratch	
2	Corner Bumper / Back Left	Paint / Scratch / Scuff	
3	Rim / Back Right	Out of Bodywork / Scratch	
4	Rim / Front Right	Out of Bodywork / Scratch	
5	Other	Paint / Poor Previous Repair	



1. Rim / Back Left
Out of Bodywork / Scratch -



2. Corner Bumper / Back Left
Paint / Scratch / Scuff -



3. Rim / Back Right
Out of Bodywork / Scratch -



4. Rim / Front Right
Out of Bodywork / Scratch -



5.
Paint / Poor Previous Repair -

Mechanical Condition

Engine

Engine Starts	✓	Engine Status / EML	✓
Engine Leak Visible	✓		

Control Lights

ABS Warning Light	✓	ESP Fault/Traction Control Malfunction Light	✓
Airbag Warning Light	✓	Oil Pressure Warning Light	✓
Power Steering Warning Light	✓	Brake Warning Light	✓
Alternator / Battery	✓	All - wheel Drive	✓
No Dashboard Lights	✓	Display Defect	✓
Service Light	✓	Tire Pressure Monitoring System	✓

Gearbox

Gear Box	✓
----------	---

Levels

Brakes Fluid	✓	Coolant Fluid	✓
--------------	---	---------------	---

Equipments Test

Central Locking	✓	Electric Windows	✓
Audio Equipment	✓	Parking Sensors / Cameras Functioning	✓
AC / Heating System	✓		

Test Drive Inspection

Engine			
Engine Noise	✓	The Gears Scratch / Skip / Abnormal Operation	✓
Fume Quantity	✓	Power Loss	✓
Brake			
Brake System Anomaly	✓		
Steering Wheel			
Steering Noise / Anomaly	✓		
Clutch			
Clutch Functioning	✓		
General			

Test Driven Status NA

- ✓ *No troubles detected, good condition or correct tests, according to vehicle age and mileage*
- ! *Damages or malfunction detected that requires repairs by the buyer*
- NA *Not applicable*
- ☐ *Not tested*

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description. [User Guide](#)