



## OPEL Corsa Corsa 1.4 16V

VIN NO W0L0SDL08B6109908

Registration Number 08B6109908



MOT Date



Last Service

2024-03-26

Number of Owners



Last Service Mileage

139355

Number of Keys



First Registration Date

2011-06-30

Odometer Reading



Country First Registered



148348 km

### Inspection Report Summary

Customer

BCA Online

Report Number

P20250902140821

Inspection Date / Place

2025-09-02 / Dürkop  
Braunschweig Nord

Cosmetic Grade

1

### Vehicle Summary

Vehicle Condition

Runner

VAT Type

Margin

Fuel Type

Petrol

Road Worthy

Yes

Colour

Black

Engine Size (cc)

1398

Engine Size

1.4

No of Doors

3

Body Type

Sedan

Drive Train

Front

Seat Colour

No of Seats

5

Seat Covering Name

Seat Covering

Cloth

Charging Cables

NEDC CO2 Rating (q/km)

134

Gearbox Type

Manual

### Vehicle History & Documents

Service Book Available

Present

Next Service Mileage

km

Previous Usage

Imported

No

Manufacturer Warrenty









Equipment

Airbag Status	Anti-lock braking	Front fog lamps	Remote adjusting wing mirrors
Stability control	Central locking	Radio	Rear parking sensors
Alloys wheels	Enhanced speaker system	Heated wing mirrors	Sports seats
CD Player	Leather steering wheel	Rain sensitive windscreen wipers	

Equipment Details


Air Conditioning	Yes	Alloy Wheel Size	17
Seat Heating	Front		

Wheels & Tyres

Right Front Tyre Depth	5	Left Front Tyre Depth	5
Right Rear Tyre Depth	5	Left Rear Tyre Depth	4



Cosmetic Damage



Component		Damage	Comments
1	Rim / Back Left	Out of Bodywork / Scratch	
2	Corner Bumper / Back Left	Paint / Scratch / Scuff	
3	Rim / Back Right	Out of Bodywork / Scratch	
4	Rim / Front Right	Out of Bodywork / Scratch	
5	Other	Paint / Poor Previous Repair	



1. Rim / Back Left  
Out of Bodywork / Scratch -



2. Corner Bumper / Back Left  
Paint / Scratch / Scuff -



3. Rim / Back Right  
Out of Bodywork / Scratch -



4. Rim / Front Right  
Out of Bodywork / Scratch -



5.  
Paint / Poor Previous Repair -

## Mechanical Condition

### Control Lights

Display Defect	✓	Service Light	✓
ABS Warning Light	✓	ESP Fault/Traction Control Malfunction Light	✓
Airbag Warning Light	✓	Oil Pressure Warning Light	✓
Power Steering Warning Light	✓	Brake Warning Light	✓
Alternator / Battery	✓	All - wheel Drive	✓
No Dashboard Lights	✓	Tire Pressure Monitoring System	✓

### Engine

Engine Starts	✓	Engine Status / EML	✓
Engine Leak Visible	✓		

### Equipments Test

Central Locking	✓	Electric Windows	✓
Audio Equipment	✓	Parking Sensors / Cameras Functioning	✓
AC / Heating System	✓		

### Gearbox

Gear Box	✓
----------	---

### Levels

Brakes Fluid	✓	Coolant Fluid	✓
--------------	---	---------------	---



Test Drive Inspection

Steering Wheel			
Steering   Noise / Anomaly		✓	
Clutch			
Clutch Functioning		✓	
Engine			
Engine Noise	✓	The Gears Scratch / Skip / Abnormal Operation	✓
Fume Quantity	✓	Power Loss	✓
Brake			
Brake System Anomaly		✓	
General			

Test Driven Status NA

- ✓ No troubles detected, good condition or correct tests, according to vehicle age and mileage
- ! Damages or malfunction detected that requires repairs by the buyer
- NA Not applicable
- ⊠ Not tested

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description. [User Guide](#)