



OPEL Corsa

Corsa 1.4 16V ecoFLEX Start-Stop

VIN NO W0L0SDL08C6004316

Registration Number 08C6004316



MOT Date

2026-12-01

Last Service

2024-11-19

Number of Owners

3

Last Service Mileage

199723

Number of Keys

2

First Registration Date

2011-09-28

Odometer Reading

216936 km

Country First Registered

Germany

Inspection Report Summary

Customer	BCA Online	Report Number	P20250919140259
Inspection Date / Place	2025-09-19 / BCA Heidenheim	Cosmetic Grade	3

Vehicle Summary


Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Petrol	Road Worthy	Yes
Colour	Silver	Engine Size (cc)	1398
Engine Size	1.4	No of Doors	3
Body Type	Sedan	Drive Train	Front
Seat Colour		No of Seats	5
Seat Covering Name		Seat Covering	Cloth
Charging Cables		NEDC CO2 Rating (q/km)	124
Gearbox Type	Manual		

Vehicle History & Documents

Service Book Available	Present	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warrenty			







Equipment

Airbag Status	Anti-lock braking	Remote adjusting wing mirrors	Leather steering wheel
Alloys wheels	Front fog lamps	Remote central locking	Radio

Equipment Details


Air Conditioning	Yes	Alloy Wheel Size	15
Extra Wheel / Tyre Set	Winter Tyres - Steel		

Wheels & Tyres


Extra Wheel - 1 Tyre Depth	6	Extra Wheel - 2 Tyre Depth	6
Extra Wheel - 3 Tyre Depth	8	Extra Wheel - 4 Tyre Depth	8
Right Front Tyre Depth	4	Left Front Tyre Depth	4
Right Rear Tyre Depth	8	Left Rear Tyre Depth	8

Cosmetic Damage

13 Schäden



3 Schäden




Component		Damage	Comments
1	Gear Knob	Interior / Scratched	
2	Ignition Key	Interior / Not Working	
3	Luggage Space Cover / Back	Interior / Ripped	
4	Bumper / Back	Bodywork / Assembly	
5	Door / Front Left	Bodywork / Dent / Dent	
6	Windshield / Front	Glass Break / Impact	
7	Front Light / Front Left	Glass Break	
8	Front Light / Front Right	Glass Break	
9	Bumper / Back	Bodywork / Dent / Dent	
10	Rim / Back Left	Out of Bodywork / Scratch	
11	Door / Front Left	Paint / Scratch / Scuff	
12	Fender / Front Left	Paint / Scratch / Scuff	

13	Hood	Paint / Scratch / Scuff
14	Hood	Paint / Stone Chip
15	Mirror Shell / Front Right	Paint / Scratch / Scuff
16	Side Panel / Back Right	Bodywork / Dent / Dent




1. Gear Knob
Interior / Scratched -



2. Ignition Key
Interior / Not Working -



3. Luggage Space Cover / Back
Interior / Ripped -



4. Bumper / Back
Bodywork / Assembly -



5. Door / Front Left
Bodywork / Dent / Dent -



6. Windshield / Front
Glass Break / Impact -



7. Front Light / Front Left
Glass Break -



8. Front Light / Front Right
Glass Break -




9. Bumper / Back
Bodywork / Dent / Dent -



10. Rim / Back Left
Out of Bodywork / Scratch -




11. Door / Front Left
Paint / Scratch / Scuff -



12. Fender / Front Left
Paint / Scratch / Scuff -




13. Hood
Paint / Scratch / Scuff -



14. Hood
Paint / Stone Chip -



15. Mirror Shell / Front Right
Paint / Scratch / Scuff -



16. Side Panel / Back Right
Bodywork / Dent / Dent -

Mechanical Condition

Control Lights

ABS Warning Light	✓	Airbag Warning Light	✓
Oil Pressure Warning Light	✓	Brake Warning Light	✓
Power Steering Warning Light	✓	Alternator / Battery	✓
No Dashboard Lights	✓	Display Defect	✓
Service Light	✓		

Engine

Engine Status / EML	✓	Engine Leak Visible	✓
Engine Starts	✓		

Gearbox

Gear Box	✓
----------	---

Levels

Brakes Fluid	✓	Coolant Fluid	✓
--------------	---	---------------	---

Equipments Test

Central Locking	✓	Main & Spare Keys Functioning	✓
Electric Windows	✓	Audio Equipment	✓
AC / Heating System	✓		

Test Drive Inspection

Steering Wheel			
Steering Noise / Anomaly		✓	
Engine			
Engine Noise	✓	The Gears Scratch / Skip / Abnormal Operation	✓
Fume Quantity	✓	Power Loss	✓
Clutch			
Clutch Functioning		✓	
General			
Test Driven Status		✓	
✓ No troubles detected, good condition or correct tests, according to vehicle age and mileage			
! Damages or malfunction detected that requires repairs by the buyer			
NA Not applicable			
= Not tested			

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description.

[User Guide](#)