



# OPEL Corsa

## Corsa 1.2 16V ecoFLEX

VIN NO W0L0SDL08E6011501  
Registration Number 08E6011501



MOT Date	Number of Owners	Number of Keys	Odometer Reading
2024-09-01	3	2	189843 km
Last Service	Last Service Mileage	First Registration Date	Country First Registered
-	-	2013-11-13	Germany

### Inspection Report Summary

Customer	BCA Online	Report Number	P20251008152435
Inspection Date / Place	2025-10-08 / SULOJA Brackel	Cosmetic Grade	4

### Vehicle Summary

Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Petrol	Road Worthy	Unknown
Colour	Grey	Engine Size (cc)	1229
Engine Size	1.2	No of Doors	3
Body Type	Sedan	Drive Train	Front
Seat Colour		No of Seats	5
Seat Covering Name		Seat Covering	Cloth
Charging Cables		NEDC CO2 Rating (q/km)	129
Gearbox Type	Manual		

### Vehicle History & Documents

Service Book Available	-	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warrenty			







Equipment

Trip Computer	Alloys wheels	Auxiliary Socket	Remote adjusting wing mirrors
Split folding rear seats	CD Player	Radio	Airbag Status
Anti-lock braking	Bluetooth telephone interface	Remote central locking	Stability control
Leather steering wheel	Rain sensitive windscreen wipers		

Equipment Details


Air Conditioning	Yes	Alloy Wheel Size	16
Seat Heating	No		

Wheels & Tyres


Right Rear Tyre Depth	4	Left Rear Tyre Depth	4
Right Front Tyre Depth	4	Left Front Tyre Depth	4

Cosmetic Damage

20 Schäden



3 Schäden




Component		Damage	Comments
1	Rim / Back Right	Out of Bodywork / Scratch	
2	Rim / Front Left	Out of Bodywork / Scratch	
3	Rim / Front Right	Out of Bodywork / Scratch	
4	Bumper / Front	Paint / Scratch / Scuff	
5	Dashboard / Front	Interior / Scratched	
6	Door / Front Right	Paint / Scratch / Scuff	
7	Side Panel / Back Left	Bodywork / Dent / Dent	
8	Hood	Bodywork / Dent / Dent	
9	Trunk Tailgate Handle / Back	Missing Part	
10	Door / Front Left	Paint / Scratch / Scuff	
11	Tailgate	Paint / Poor Previous Repair	
12	Bumper / Front	Paint / Scratch / Scuff	

13	Mirror / Front Right	Paint / Scratch / Scuff
14	Rim / Back Left	Out of Bodywork / Scratch
15	Fender / Front Left	Bodywork / Dent / Dent
16	Roof	Bodywork / Dent / Dent
17	Bumper / Back	Paint / Scratch / Scuff
18	Door / Front Left	Paint / Scratch / Scuff
19	Gear Knob	Interior / Scratched
20	Windshield / Front	Glass Break
21	Side Panel / Back Right	Bodywork / Dent / Dent
22	Gear Knob	Interior / Scratched
23	Tailgate	Bodywork / Dent / Dent



1. Rim / Back Right  
Out of Bodywork / Scratch -



2. Rim / Front Left  
Out of Bodywork / Scratch -




3. Rim / Front Right  
Out of Bodywork / Scratch -




4. Bumper / Front  
Paint / Scratch / Scuff -




5. Dashboard / Front  
Interior / Scratched -



6. Door / Front Right  
Paint / Scratch / Scuff -




7. Side Panel / Back Left  
Bodywork / Dent / Dent -



8. Hood  
Bodywork / Dent / Dent -




9. Trunk Tailgate Handle / Back  
Missing Part -



10. Door / Front Left  
Paint / Scratch / Scuff -



11. Tailgate  
Paint / Poor Previous Repair -



12. Bumper / Front  
Paint / Scratch / Scuff -




13. Mirror / Front Right  
Paint / Scratch / Scuff -



14. Rim / Back Left  
Out of Bodywork / Scratch -



15. Fender / Front Left  
Bodywork / Dent / Dent -



16. Roof  
Bodywork / Dent / Dent -




17. Bumper / Back  
Paint / Scratch / Scuff -



18. Door / Front Left  
Paint / Scratch / Scuff -



19. Gear Knob  
Interior / Scratched -



20. Windshield / Front  
Glass Break -



21. Side Panel / Back Right  
Bodywork / Dent / Dent -



22. Gear Knob  
Interior / Scratched -



23. Tailgate  
Bodywork / Dent / Dent -

## Mechanical Condition

### Control Lights

ABS Warning Light	✓	ESP Fault/Traction Control Malfunction Light	✓
Airbag Warning Light	✓	Oil Pressure Warning Light	✓
Brake Warning Light	✓	Power Steering Warning Light	✓
Alternator / Battery	✓	No Dashboard Lights	✓
Display Defect	✓	Tire Pressure Monitoring System	✓

### Engine

Engine Status / EML	✓	Engine Leak Visible	✓
Engine Starts	✓		

### Gearbox

Gear Box	✓
----------	---

### Equipments Test

Electric Windows	✓	Audio Equipment	✓
AC / Heating System	✓	Main & Spare Keys Functioning	✓

### Levels

Brakes Fluid	✓	Coolant Fluid	✓
--------------	---	---------------	---

Test Drive Inspection

Steering Wheel

Steering | Noise / Anomaly

Engine

Engine Noise The Gears Scratch / Skip / Abnormal Operation

Fume Quantity Power Loss

Brake

Brake System Anomaly

Clutch

Clutch Functioning

General

Test Driven Status

- No troubles detected, good condition or correct tests, according to vehicle age and mileage
- Damages or malfunction detected that requires repairs by the buyer
- Not applicable
- Not tested

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description. [User Guide](#)