



OPEL Corsa
Corsa 1.2 16V
VIN NO W0L0XCF0846130701
Registration Number 0846130701



MOT Date



Last Service



Number of Owners




Last Service Mileage



Number of Keys



First Registration Date



Odometer Reading



75155 km

Country First Registered



Inspection Report Summary

Customer	BCA Online	Report Number	P20250908154711
Inspection Date / Place	2025-09-08 / Dello Eppendorf/Hamburg	Cosmetic Grade	5

Vehicle Summary

Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Petrol	Road Worthy	Yes
Colour	Blue	Engine Size (cc)	1199
Engine Size	1.2	No of Doors	3
Body Type	Sedan	Drive Train	Front
Seat Colour		No of Seats	5
Seat Covering Name	Schwarz	Seat Covering	Cloth
Charging Cables		NEDC CO2 Rating (q/km)	143
Gearbox Type	Manual		

Vehicle History & Documents

Service Book Available	Missing	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warranty			







Equipment

Trip Computer	Anti-lock braking	Radio	Airbag Status
Remote adjusting wing mirrors			

Equipment Details


Air Conditioning	Yes
------------------	-----

Wheels & Tyres


Right Front Tyre Depth	4	Left Front Tyre Depth	4
Right Rear Tyre Depth	5	Left Rear Tyre Depth	5

Cosmetic Damage

28 Schäden



3 Schäden



Component		Damage	Comments
1	Fender / Front Left	Bodywork / Dent / Dent	
2	Fender / Front Left	Paint / Scratch / Scuff	
3	Door / Front Left	Paint / Scratch / Scuff	
4	Door / Front Left	Paint / Scratch / Scuff	
5	Fender / Back Left	Paint / Scratch / Scuff	
6	Fender / Back Left	Paint / Scratch / Scuff	
7	Roof	Paint / Chemical Damage	
8	Bumper / Back	Paint / Scratch / Scuff	
9	Bumper / Back	Bodywork / Breakage / Crack	
10	Bumper / Back	Bodywork / Breakage / Crack	
11	Tailgate	Bodywork / Dent / Dent	
12	Fender / Back Right	Paint / Scratch / Scuff	

13	Fender / Back Right	Bodywork / Dent / Dent
14	Fender / Back Right	Paint / Scratch / Scuff
15	Fender / Back Right	Paint / Scratch / Scuff
16	Fender / Back Right	Paint / Scratch / Scuff
17	Door / Front Right	Bodywork / Dent / Dent
18	Door / Front Right	Paint / Scratch / Scuff
19	Bumper / Front	Paint / Scratch / Scuff
20	Hood	Bodywork / Dent / Dent
21	Hood	Paint / Corrosion
22	Hood	Paint / Chemical Damage
23	Pillar / Front Left	Paint / Chipping
24	Panel Filling / Front Left	Interior / Loose
25	Panel Filling / Front Right	Interior / Loose
26	Roof	Paint / Corrosion
27	Roof	Paint / Chipping
28	Gear Knob	Interior / Broken
29	Pillar / Front Left	Paint / Corrosion



1. Fender / Front Left
Bodywork / Dent / Dent -




2. Fender / Front Left
Paint / Scratch / Scuff -




3. Door / Front Left
Paint / Scratch / Scuff -




4. Door / Front Left
Paint / Scratch / Scuff -



5. Fender / Back Left
Paint / Scratch / Scuff -



6. Fender / Back Left
Paint / Scratch / Scuff -



7. Roof
Paint / Chemical Damage -




8. Bumper / Back
Paint / Scratch / Scuff -



9. Bumper / Back
Bodywork / Breakage / Crack -




10. Bumper / Back
Bodywork / Breakage / Crack -




11. Tailgate
Bodywork / Dent / Dent -




12. Fender / Back Right
Paint / Scratch / Scuff -




13. Fender / Back Right
Bodywork / Dent / Dent -




14. Fender / Back Right
Paint / Scratch / Scuff -




15. Fender / Back Right
Paint / Scratch / Scuff -



16. Fender / Back Right
Paint / Scratch / Scuff -




17. Door / Front Right
Bodywork / Dent / Dent -



18. Door / Front Right
Paint / Scratch / Scuff -



19. Bumper / Front
Paint / Scratch / Scuff -



20. Hood
Bodywork / Dent / Dent -




21. Hood
Paint / Corrosion -



22. Hood
Paint / Chemical Damage -




23. Pillar / Front Left
Paint / Chipping -




24. Panel Filling / Front Left
Interior / Loose -



25. Panel Filling / Front Right
Interior / Loose -



26. Roof
Paint / Corrosion -



27. Roof
Paint / Chipping -



28. Gear Knob
Interior / Broken -



29. Pillar / Front Left
Paint / Corrosion -

Mechanical Condition

Control Lights

Display Defect	✓	ABS Warning Light	✓
Airbag Warning Light	✓	Oil Pressure Warning Light	✓
Brake Warning Light	✓	Power Steering Warning Light	✓
Alternator / Battery	✓		

Engine

Engine Status / EML	✓	Engine Leak Visible	!
Engine Starts	✓		

Gearbox

Gear Box	✓
----------	---

Equipments Test

Audio Equipment	✓	AC / Heating System	✓
Other Equipments	✓		

Levels

Brakes Fluid	✓	Coolant Fluid	✓
--------------	---	---------------	---

Test Drive Inspection

Steering Wheel

Steering | Noise / Anomaly

Engine

Engine Noise The Gears Scratch / Skip / Abnormal Operation

Fume Quantity Power Loss

Brake

Brake System Anomaly

Clutch

Clutch Functioning

General

Test Driven Status

- No troubles detected, good condition or correct tests, according to vehicle age and mileage
- Damages or malfunction detected that requires repairs by the buyer
- Not applicable
- Not tested

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description. [User Guide](#)