



OPEL Corsa Corsa 1.4 Turbo (ecoFLEX) Start/Stop

VIN NO W0L0XEP08F6019893

Registration Number 08F6019893



MOT Date



Last Service

2025-04-02

Number of Owners



Last Service Mileage

178815

Number of Keys



First Registration Date

2015-02-26

Odometer Reading



182994 km

Country First Registered



Inspection Report Summary

Customer	BCA Online	Report Number	P20250903133143
Inspection Date / Place	2025-09-03 / Dello Billstedt/ Hamburg	Cosmetic Grade	3

Vehicle Summary

Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Petrol	Road Worthy	Yes
Colour	White	Engine Size (cc)	1364
Engine Size	1.4	No of Doors	3
Body Type	Sedan	Drive Train	Front
Seat Colour		No of Seats	5
Seat Covering Name	Schwarz	Seat Covering	Cloth
Charging Cables		NEDC CO2 Rating (q/km)	125
Gearbox Type	Manual		

Vehicle History & Documents

Service Book Available	Full Service History	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warranty			







Equipment

Tinted Glass	USB Socket	Alloys wheels	Auxiliary Socket
Cruise control	Remote adjusting wing mirrors	Split folding rear seats	Leather steering wheel
Rear parking sensors	Trip Computer	Airbag Status	Anti-lock braking
Bluetooth telephone interface	Front fog lamps	Remote central locking	Stability control
Radio			

Equipment Details


Air Conditioning	Climate Control	Alloy Wheel Size	16
Seat Heating	Front		

Wheels & Tyres


Right Front Tyre Depth	4	Left Front Tyre Depth	4
Right Rear Tyre Depth	5	Left Rear Tyre Depth	5

Cosmetic Damage

11 Schäden



3 Schäden



Component		Damage	Comments
1	Rocker Panel / Center Left	Bodywork / Dent / Dent	
2	Door / Front Left	Bodywork / Dent / Dent	
3	Mirror / Front Left	Paint / Scratch / Scuff	
4	Rim / Front Left	Out of Bodywork / Scratch	
5	Hood	Paint / Stone Chip	
6	Hood	Paint / Stone Chip	
7	Mirror / Front Right	Paint / Scratch / Scuff	
8	Rim / Front Right	Out of Bodywork / Scratch	
9	Window Cover / Back Right	Paint / Scratch / Scuff	
10	Fender / Back Right	Paint / Scratch / Scuff	
11	Bumper / Back	Paint / Scratch / Scuff	
12	Seat / Front Left	Interior / Ripped	

13	Steering Wheel / Front	Interior / Scraped
----	------------------------	--------------------

14	Center Console	Interior / Worn - out
----	----------------	-----------------------



1. Rocker Panel / Center Left
Bodywork / Dent / Dent -




2. Door / Front Left
Bodywork / Dent / Dent -




3. Mirror / Front Left
Paint / Scratch / Scuff -



4. Rim / Front Left
Out of Bodywork / Scratch -



5. Hood
Paint / Stone Chip -



6. Hood
Paint / Stone Chip -



7. Mirror / Front Right
Paint / Scratch / Scuff -



8. Rim / Front Right
Out of Bodywork / Scratch -



9. Window Cover / Back Right
Paint / Scratch / Scuff -



10. Fender / Back Right
Paint / Scratch / Scuff -



11. Bumper / Back
Paint / Scratch / Scuff -



12. Seat / Front Left
Interior / Ripped -



13. Steering Wheel / Front
Interior / Scraped -



14. Center Console
Interior / Worn - out -

Mechanical Condition

Control Lights

Display Defect	✓	Service Light	✓
ABS Warning Light	✓	ESP Fault/Traction Control Malfunction Light	✓
Airbag Warning Light	✓	Oil Pressure Warning Light	✓
Brake Warning Light	✓	Power Steering Warning Light	✓
Alternator / Battery	✓	No Dashboard Lights	✓
Tire Pressure Monitoring System	✓		

Equipments Test

Central Locking	✓	Main & Spare Keys Functioning	!
Electric Windows	✓	Audio Equipment	✓
Parking Sensors / Cameras Functioning	✓	AC / Heating System	✓
Other Equipments	✓		

Engine

Engine Status / EML	!	Engine Leak Visible	✓
Engine Starts	✓		

Gearbox

Gear Box	✓
----------	---

Levels

Brakes Fluid	✓	Coolant Fluid	✓
--------------	---	---------------	---

Test Drive Inspection

Steering Wheel

Steering | Noise / Anomaly

Engine

Engine Noise	NA	The Gears Scratch / Skip / Abnormal Operation	NA
Fume Quantity		Power Loss	

Clutch

Clutch Functioning

Brake

Brake System Anomaly NA

General

Test Driven Status NA

- No troubles detected, good condition or correct tests, according to vehicle age and mileage
- Damages or malfunction detected that requires repairs by the buyer
- NA Not applicable
- Not tested

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description. [User Guide](#)