



OPEL Corsa Corsa 1.2

VIN NO W0L0XEP08H6044873

Registration Number 08H6044873



MOT Date



Last Service

2025-08-08

Number of Owners



3

Last Service Mileage

137156

Number of Keys



2

First Registration Date

2017-02-14

Odometer Reading



137156 km

Country First Registered



-

Inspection Report Summary

Customer	BCA Online	Report Number	P20250903130509
Inspection Date / Place	2025-09-03 / Dello Billstedt/ Hamburg	Cosmetic Grade	5

Vehicle Summary




Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Petrol	Road Worthy	Yes
Colour	Red	Engine Size (cc)	1229
Engine Size	1.2	No of Doors	3
Body Type	Sedan	Drive Train	Front
Seat Colour		No of Seats	5
Seat Covering Name	Schwarz	Seat Covering	Cloth
Charging Cables		NEDC CO2 Rating (q/km)	129
Gearbox Type	Manual		

Vehicle History & Documents

Service Book Available	Full Service History	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warrenty			







Equipment

Trip Computer	Anti-lock braking	Remote adjusting wing mirrors	Stability control
Airbag Status	Auxiliary Socket	Remote central locking	Radio

Equipment Details


Air Conditioning	Yes	Seat Heating	No
------------------	-----	--------------	----

Wheels & Tyres


Right Front Tyre Depth	2	Left Front Tyre Depth	2
Right Rear Tyre Depth	5	Left Rear Tyre Depth	5

Cosmetic Damage

25 Schäden




1 Schäden




Component		Damage	Comments
1	Door / Front Left	Bodywork / Dent / Dent	
2	Door / Front Left	Paint / Scratch / Scuff	
3	Door / Front Left	Paint / Chipping	
4	Door / Front Left	Paint / Scratch / Scuff	
5	Mirror / Front Left	Paint / Scratch / Scuff	
6	Fender / Back Left	Bodywork / Dent / Dent	
7	Fender / Back Left	Bodywork / Dent / Dent	
8	Fender / Back Left	Bodywork / Dent / Dent	
9	Fender / Back Left	Paint / Scratch / Scuff	
10	Bumper / Back	Paint / Scratch / Scuff	
11	Bumper / Back	Paint / Scratch / Scuff	
12	Fender / Back Right	Paint / Scratch / Scuff	


13	Fender / Back Right	Paint / Scratch / Scuff
14	Fender / Back Right	Paint / Scratch / Scuff
15	Fender / Back Right	Paint / Scratch / Scuff
16	Door / Front Right	Paint / Scratch / Scuff
17	Door / Front Right	Paint / Scratch / Scuff
18	Mirror / Front Right	Paint / Scratch / Scuff
19	Door Step / Front Right	Interior / Scratched
20	Bumper / Front	Paint / Scratch / Scuff
21	Bumper / Front	Paint / Scratch / Scuff
22	Bumper / Front	Paint / Scratch / Scuff
23	Bumper / Front	Paint / Scratch / Scuff
24	Bumper / Front	Paint / Scratch / Scuff
25	Hood	Paint / Stone Chip
26	Hood	Paint / Stone Chip



1. Door / Front Left
Bodywork / Dent / Dent -




2. Door / Front Left
Paint / Scratch / Scuff -




3. Door / Front Left
Paint / Chipping -




4. Door / Front Left
Paint / Scratch / Scuff -



5. Mirror / Front Left
Paint / Scratch / Scuff -



6. Fender / Back Left
Bodywork / Dent / Dent -



7. Fender / Back Left
Bodywork / Dent / Dent -




8. Fender / Back Left
Bodywork / Dent / Dent -



9. Fender / Back Left
Paint / Scratch / Scuff -



10. Bumper / Back
Paint / Scratch / Scuff -



11. Bumper / Back
Paint / Scratch / Scuff -



12. Fender / Back Right
Paint / Scratch / Scuff -



13. Fender / Back Right
Paint / Scratch / Scuff -




14. Fender / Back Right
Paint / Scratch / Scuff -




15. Fender / Back Right
Paint / Scratch / Scuff -



16. Door / Front Right
Paint / Scratch / Scuff -



17. Door / Front Right
Paint / Scratch / Scuff -




18. Mirror / Front Right
Paint / Scratch / Scuff -



19. Door Step / Front Right
Interior / Scratched -




20. Bumper / Front
Paint / Scratch / Scuff -



21. Bumper / Front
Paint / Scratch / Scuff -




22. Bumper / Front
Paint / Scratch / Scuff -



23. Bumper / Front
Paint / Scratch / Scuff -



24. Bumper / Front
Paint / Scratch / Scuff -



25. Hood
Paint / Stone Chip -



26. Hood
Paint / Stone Chip -

Mechanical Condition

Control Lights

ABS Warning Light	✓	ESP Fault/Traction Control Malfunction Light	✓
Airbag Warning Light	✓	Oil Pressure Warning Light	✓
Brake Warning Light	✓	Power Steering Warning Light	✓
Alternator / Battery	✓	No Dashboard Lights	✓
Display Defect	✓	Service Light	✓
Tire Pressure Monitoring System	✓		

Engine

Engine Status / EML	✓	Engine Leak Visible	✓
Engine Starts	✓		

Gearbox

Gear Box	✓
----------	---

Levels

Brakes Fluid	✓	Coolant Fluid	✓
--------------	---	---------------	---

Equipments Test

Central Locking	✓	Main & Spare Keys Functioning	✓
Electric Windows	✓	Audio Equipment	✓
AC / Heating System	✓	Other Equipments	✓

Test Drive Inspection

Engine			
Engine Noise	NA	The Gears Scratch / Skip / Abnormal Operation	NA
Fume Quantity	✓	Power Loss	✓
Brake			
Brake System Anomaly	NA		
Steering Wheel			
Steering Noise / Anomaly	✓		
Clutch			
Clutch Functioning	✓		
General			

Test Driven Status NA

- ✓ No troubles detected, good condition or correct tests, according to vehicle age and mileage
- ! Damages or malfunction detected that requires repairs by the buyer
- NA Not applicable
- ☐ Not tested

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description. [User Guide](#)