



## OPEL Corsa Corsa 1.2

VIN NO W0L0XEP08H6044873

Registration Number 08H6044873



MOT Date



Last Service

2025-08-08

Number of Owners



Last Service Mileage

137156

Number of Keys



First Registration Date

2017-02-14

Odometer Reading



137156 km

Country First Registered



### Inspection Report Summary

|                         |                                          |                |                 |
|-------------------------|------------------------------------------|----------------|-----------------|
| Customer                | BCA Online                               | Report Number  | P20250903130509 |
| Inspection Date / Place | 2025-09-03 / Dello Billstedt/<br>Hamburg | Cosmetic Grade | 5               |

### Vehicle Summary


|                    |         |                        |        |
|--------------------|---------|------------------------|--------|
| Vehicle Condition  | Runner  | VAT Type               | Margin |
| Fuel Type          | Petrol  | Road Worthy            | Yes    |
| Colour             | Red     | Engine Size (cc)       | 1229   |
| Engine Size        | 1.2     | No of Doors            | 3      |
| Body Type          | Sedan   | Drive Train            | Front  |
| Seat Colour        |         | No of Seats            | 5      |
| Seat Covering Name | Schwarz | Seat Covering          | Cloth  |
| Charging Cables    |         | NEDC CO2 Rating (q/km) | 129    |
| Gearbox Type       | Manual  |                        |        |




### Vehicle History & Documents

|                        |                      |                      |    |
|------------------------|----------------------|----------------------|----|
| Service Book Available | Full Service History | Next Service Mileage | km |
| Previous Usage         |                      | Imported             | No |
| Manufacturer Warrenty  |                      |                      |    |











Equipment

|               |                   |                               |                   |
|---------------|-------------------|-------------------------------|-------------------|
| Trip Computer | Anti-lock braking | Remote adjusting wing mirrors | Stability control |
| Airbag Status | Auxiliary Socket  | Remote central locking        | Radio             |

Equipment Details


|                  |     |              |    |
|------------------|-----|--------------|----|
| Air Conditioning | Yes | Seat Heating | No |
|------------------|-----|--------------|----|

Wheels & Tyres


|                        |   |                       |   |
|------------------------|---|-----------------------|---|
| Right Front Tyre Depth | 2 | Left Front Tyre Depth | 2 |
| Right Rear Tyre Depth  | 5 | Left Rear Tyre Depth  | 5 |

Cosmetic Damage

25 Schäden




1 Schäden




| Component |                     | Damage                  | Comments |
|-----------|---------------------|-------------------------|----------|
| 1         | Door / Front Left   | Bodywork / Dent / Dent  |          |
| 2         | Door / Front Left   | Paint / Scratch / Scuff |          |
| 3         | Door / Front Left   | Paint / Chipping        |          |
| 4         | Door / Front Left   | Paint / Scratch / Scuff |          |
| 5         | Mirror / Front Left | Paint / Scratch / Scuff |          |
| 6         | Fender / Back Left  | Bodywork / Dent / Dent  |          |
| 7         | Fender / Back Left  | Bodywork / Dent / Dent  |          |
| 8         | Fender / Back Left  | Bodywork / Dent / Dent  |          |
| 9         | Fender / Back Left  | Paint / Scratch / Scuff |          |
| 10        | Bumper / Back       | Paint / Scratch / Scuff |          |
| 11        | Bumper / Back       | Paint / Scratch / Scuff |          |
| 12        | Fender / Back Right | Paint / Scratch / Scuff |          |


|    |                         |                         |
|----|-------------------------|-------------------------|
| 13 | Fender / Back Right     | Paint / Scratch / Scuff |
| 14 | Fender / Back Right     | Paint / Scratch / Scuff |
| 15 | Fender / Back Right     | Paint / Scratch / Scuff |
| 16 | Door / Front Right      | Paint / Scratch / Scuff |
| 17 | Door / Front Right      | Paint / Scratch / Scuff |
| 18 | Mirror / Front Right    | Paint / Scratch / Scuff |
| 19 | Door Step / Front Right | Interior / Scratched    |
| 20 | Bumper / Front          | Paint / Scratch / Scuff |
| 21 | Bumper / Front          | Paint / Scratch / Scuff |
| 22 | Bumper / Front          | Paint / Scratch / Scuff |
| 23 | Bumper / Front          | Paint / Scratch / Scuff |
| 24 | Bumper / Front          | Paint / Scratch / Scuff |
| 25 | Hood                    | Paint / Stone Chip      |
| 26 | Hood                    | Paint / Stone Chip      |



1. Door / Front Left  
Bodywork / Dent / Dent -




2. Door / Front Left  
Paint / Scratch / Scuff -




3. Door / Front Left  
Paint / Chipping -



4. Door / Front Left  
Paint / Scratch / Scuff -




5. Mirror / Front Left  
Paint / Scratch / Scuff -




6. Fender / Back Left  
Bodywork / Dent / Dent -





7. Fender / Back Left  
Bodywork / Dent / Dent -




8. Fender / Back Left  
Bodywork / Dent / Dent -



9. Fender / Back Left  
Paint / Scratch / Scuff -



10. Bumper / Back  
Paint / Scratch / Scuff -



11. Bumper / Back  
Paint / Scratch / Scuff -



12. Fender / Back Right  
Paint / Scratch / Scuff -





13. Fender / Back Right  
Paint / Scratch / Scuff -




14. Fender / Back Right  
Paint / Scratch / Scuff -




15. Fender / Back Right  
Paint / Scratch / Scuff -



16. Door / Front Right  
Paint / Scratch / Scuff -



17. Door / Front Right  
Paint / Scratch / Scuff -



18. Mirror / Front Right  
Paint / Scratch / Scuff -






19. Door Step / Front Right  
Interior / Scratched -




20. Bumper / Front  
Paint / Scratch / Scuff -



21. Bumper / Front  
Paint / Scratch / Scuff -



22. Bumper / Front  
Paint / Scratch / Scuff -




23. Bumper / Front  
Paint / Scratch / Scuff -



24. Bumper / Front  
Paint / Scratch / Scuff -





25. Hood  
Paint / Stone Chip -



26. Hood  
Paint / Stone Chip -

## Mechanical Condition

### Control Lights

|                                 |   |                                              |   |
|---------------------------------|---|----------------------------------------------|---|
| Display Defect                  | ✓ | Service Light                                | ✓ |
| ABS Warning Light               | ✓ | ESP Fault/Traction Control Malfunction Light | ✓ |
| Airbag Warning Light            | ✓ | Oil Pressure Warning Light                   | ✓ |
| Brake Warning Light             | ✓ | Power Steering Warning Light                 | ✓ |
| Alternator / Battery            | ✓ | No Dashboard Lights                          | ✓ |
| Tire Pressure Monitoring System | ✓ |                                              |   |

### Equipments Test

|                     |   |                               |   |
|---------------------|---|-------------------------------|---|
| Central Locking     | ✓ | Main & Spare Keys Functioning | ✓ |
| Electric Windows    | ✓ | Audio Equipment               | ✓ |
| AC / Heating System | ✓ | Other Equipments              | ✓ |

### Engine

|                     |   |                     |   |
|---------------------|---|---------------------|---|
| Engine Status / EML | ✓ | Engine Leak Visible | ✓ |
| Engine Starts       | ✓ |                     |   |

### Gearbox

|          |   |
|----------|---|
| Gear Box | ✓ |
|----------|---|

### Levels

|              |   |               |   |
|--------------|---|---------------|---|
| Brakes Fluid | ✓ | Coolant Fluid | ✓ |
|--------------|---|---------------|---|



Test Drive Inspection

Steering Wheel

Steering | Noise / Anomaly

Engine

|               |    |                                               |    |
|---------------|----|-----------------------------------------------|----|
| Engine Noise  | NA | The Gears Scratch / Skip / Abnormal Operation | NA |
| Fume Quantity |    | Power Loss                                    |    |

Clutch

Clutch Functioning

Brake

Brake System Anomaly NA

General

Test Driven Status NA

- No troubles detected, good condition or correct tests, according to vehicle age and mileage
- Damages or malfunction detected that requires repairs by the buyer
- NA Not applicable
- Not tested

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description. [User Guide](#)