



OPEL Karl Benzina

Karl 1.0 75cv

VIN NO W0LDD6E78GC516838
Registration Number FA048PC



MOT Date

2023-09-26

Last Service



Number of Owners



Last Service Mileage



Number of Keys



First Registration Date

2015-09-10

Odometer Reading

127184 km

Country First Registered

Italy

Inspection Report Summary

Customer	BCA Lodi	Report Number	P20250925144249
Inspection Date / Place	2025-09-25 / BCA Lodi	Cosmetic Grade	5


Vehicle Summary

Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Petrol	Gearbox Type	Manual
Colour	White	Engine Size (cc)	999
Engine Size	1.0	No of Doors	5
Body Type	Sedan	Drive Train	Front
Seat Colour	Black	No of Seats	5
Seat Covering Name		Seat Covering	Cloth
Charging Cables		NEDC CO2 Rating (q/km)	104

Vehicle History & Documents

Service Book Available	-	Next Service Mileage	km
Previous Usage	Normal Use	Imported	No
Manufacturer Warrenty			







Equipment

Central locking	Digital Radio	Remote adjusting wing mirrors	Cruise control
Stability control	Power assisted steering	Parcel Shef	Remote central locking
Trip Computer			


Wheels & Tyres

Mounted Tires


Tyre / Wheel Type	Four Seasons	
	HANKOOK HANKOOK-KINERGY 4S H740	165/65//R14 - 70T / 2 mm
	HANKOOK HANKOOK-KINERGY 4S H740	165/65//R14 - 70T / 2 mm
	NOKIAN NOKIAN-WEATHERPROOF	165/65//R14 - 79T / 2 mm
	NOKIAN NOKIAN-WEATHERPROOF	165/65//R14 - 79T / 2 mm

Cosmetic Damage

18 Danni



3 Danni



1

Component		Damage	Comments
1	Dashboard / Front	Interior / Warning Light ON	
2	Aeration Grid / Front Center	Interior / Broken	
3	Windshield / Front	Glass Break / Impact	
4	Hood	Paint / Chipping	
5	Bumper / Front	Bodywork / Dent	
6	Mirror Shell / Front Left	Paint / Scratch / Line	
7	Door / Front Left	Bodywork / Dent	
8	Door / Back Left	Bodywork / Dent	
9	Fender / Back Left	Bodywork / Dent	
10	Bumper / Back	Bodywork / Breakage	
11	Tailgate	Bodywork / Dent	
12	Fender / Back Right	Bodywork / Dent	


13	Door / Back Right	Bodywork / Dent
14	Door / Front Right	Bodywork / Dent
15	Mirror Shell / Front Right	Paint / Scratch / Line
16	Fender / Front Right	Bodywork / Dent
17	Rocker Panel / Center Right	Bodywork / Dent
18	Pillar / Front Right	Bodywork / Dent / Hail Area
19	Pillar / Front Left	Bodywork / Dent / Hail Area
20	Roof	Bodywork / Dent / Hail Area
21	Cabin	Interior / Dirty



1. Dashboard / Front Interior / Warning Light ON -



2. Aeration Grid / Front Center Interior / Broken -




3. Windshield / Front Glass Break / Impact -




4. Hood Paint / Chipping -



5. Bumper / Front Bodywork / Dent -



6. Mirror Shell / Front Left Paint / Scratch / Line -



7. Door / Front Left
Bodywork / Dent -



8. Door / Back Left
Bodywork / Dent -



9. Fender / Back Left
Bodywork / Dent -




10. Bumper / Back
Bodywork / Breakage -



11. Tailgate
Bodywork / Dent -



12. Fender / Back Right
Bodywork / Dent -



13. Door / Back Right
Bodywork / Dent -



14. Door / Front Right
Bodywork / Dent -



15. Mirror Shell / Front Right
Paint / Scratch / Line -



16. Fender / Front Right
Bodywork / Dent -



17. Rocker Panel / Center Right
Bodywork / Dent -




18. Pillar / Front Right
Bodywork / Dent / Hail Area -



19. Pillar / Front Left
Bodywork / Dent / Hail Area -



20. Roof
Bodywork / Dent / Hail Area -



21. Cabin
Interior / Dirty -

Mechanical Condition

Engine			
Vehicle Start - up	✓	Engine Starts	✓
Engine Leak Visible	✓		
Clutch			
Clutch Functioning	✓		
Equipments Test			
Other Equipments	✓	AC / Heating System	✓
Levels			
Brakes Fluid	✓	Coolant Fluid	⚠

Test Drive Inspection

General			
Test Driven Status	✓	Test Drive Comment	SPIA MOTORE ACCESA.
Other Checks			
Steering	✓	Brakes	✓
Suspension	⚠		
Equipments Test			
Steering Noise / Anomaly	✓		
Engine			
Power Loss	✓	Fume Quantity	✓
Engine Noise	⚠		
Gearbox			
Manual Gearbox	✓		

✓ No troubles detected, good condition or correct tests, according to vehicle age and mileage

⚠ Damages or malfunction detected that requires repairs by the buyer

NA Not applicable

☐ Not tested