



OPEL Mokka I Benzina

Mokka 1.4 t Ego Gpl-tech 4x2 140cv E6

VIN NO W0LJC7EZ1F4020110
Registration Number EX248JA



MOT Date	Number of Owners	Number of Keys	Odometer Reading
2025-05-10	-	-	162662 km
Last Service	Last Service Mileage	First Registration Date	Country First Registered
-	-	2014-11-19	Italy

Inspection Report Summary

Customer	BCA Lodi	Report Number	P20251002113703
Inspection Date / Place	2025-10-02 / BCA Lodi	Cosmetic Grade	4



Vehicle Summary

Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	LPG	Gearbox Type	Manual
Colour	White	Engine Size (cc)	1364
Engine Size	1.4	No of Doors	5
Body Type	SUV	Drive Train	Front
Seat Colour	Black	No of Seats	5
Seat Covering Name		Seat Covering	Cloth
Charging Cables		NEDC CO2 Rating (q/km)	142

Vehicle History & Documents

Service Book Available	-	Next Service Mileage	km
Previous Usage	Normal Use	Imported	No
Manufacturer Warrenty			







Equipment


Central locking	Alloys wheels	Volante multifuncion	Remote adjusting wing mirrors
Cruise control	Tyre Mobility Kit	Power assisted steering	Digital Radio
Parcel Shef	Remote central locking	Trip Computer	Stability control

Wheels & Tyres


Mounted Tires

Tyre / Wheel Type	Summer	
	CEAT	215/60//R17 - 100V / 3 mm
	CEAT	215/60//R17 - 100V / 3 mm
	CEAT	215/60//R17 - 100V / 3 mm
	CEAT	215/60//R17 - 100V / 3 mm

20 Danni



8 Danni




1

6/13 - Report Number P20251002113703

13	Blade/spoiler / Front	Bodywork / Breakage
14	Front Light / Front Right	Glass Break / Scratch
15	Windshield / Front	Glass Break / Impact
16	Rim / Front Left	Out of Bodywork / Scratch
17	Mirror Shell / Front Left	Bodywork / Breakage
18	Door / Front Left	Bodywork / Dent
19	Tailgate	Bodywork / Dent / Small Dent
20	Bumper / Back	Paint / Scratch / Line
21	Fender / Back Right	Bodywork / Dent / Hail Area
22	Door / Back Right	Bodywork / Dent
23	Rim / Back Right	Out of Bodywork / Scratch
24	Wing Expander / Back Right	Paint / Scratch / Line
25	Roof	Bodywork / Dent / Hail Area
26	Rim / Back Left	Out of Bodywork / Scratch
27	Wing Expander / Back Left	Paint / Scratch / Line
28	Ignition Key	Interior / Broken



1. Dashboard / Front Interior / Worn - out -



2. Center Console Interior / Worn - out -



3. Panel Filling / Front Left Interior / Scratched -



5. Steering Wheel / Front Interior / Scratched -



6. Trunk Upholstery / Back Interior / Scratched -



7. Tailgate Upholstery / Back Interior / Scratched -



8. Rim / Front Right
Out of Bodywork / Scratch -



9. Mirror Shell / Front Right
Paint / Scratch / Line -



10. Door / Front Right
Bodywork / Dent -



11. Bumper / Front
Bodywork / Breakage -



12. Wing Expander / Front Right
Paint / Scratch / Line -



13. Blade/spoiler / Front
Bodywork / Breakage -




14. Front Light / Front Right
Glass Break / Scratch -



15. Windshield / Front
Glass Break / Impact -



16. Rim / Front Left
Out of Bodywork / Scratch -



17. Mirror Shell / Front Left
Bodywork / Breakage -



18. Door / Front Left
Bodywork / Dent -



19. Tailgate
Bodywork / Dent / Small Dent -



20. Bumper / Back
Paint / Scratch / Line -




21. Fender / Back Right
Bodywork / Dent / Hail Area -




22. Door / Back Right
Bodywork / Dent -



23. Rim / Back Right
Out of Bodywork / Scratch -



24. Wing Expander / Back Right
Paint / Scratch / Line -




25. Roof
Bodywork / Dent / Hail Area -



26. Rim / Back Left
Out of Bodywork / Scratch -



27. Wing Expander / Back Left
Paint / Scratch / Line -



28. Ignition Key
Interior / Broken -

Mechanical Condition

Engine			
Vehicle Start - up	✓	Engine Starts	✓
Engine Leak Visible	✓		
Clutch			
Clutch Functioning	!		
Equipments Test			
Other Equipments	✓	AC / Heating System	✓
Levels			
Brakes Fluid	✓	Coolant Fluid	!

Test Drive Inspection

Other Checks			
Steering	✓	Brakes	✓
Suspension	!		
Gearbox			
Manual Gearbox	✓		
General			
Test Driven Status	✓		
Equipments Test			
Steering Noise / Anomaly	✓		
Engine			
Power Loss	✓	Fume Quantity	✓
Engine Noise	!		
✓ No troubles detected, good condition or correct tests, according to vehicle age and mileage			
! Damages or malfunction detected that requires repairs by the buyer			
NA Not applicable			
☐ Not tested			