



|                                    |                                                    |                      |            |
|------------------------------------|----------------------------------------------------|----------------------|------------|
| Brand:                             | Opel                                               | Mileage(km):         | 192177     |
| Model:                             | Astra Sports Tourer                                | Number of doors:     | 5          |
| Model type:                        | 1.4 Aut. Turbo Sport   Org.NL                      | Vehicle length (cm): |            |
| License plate:                     | 99XNT3                                             | Vehicle width (cm):  |            |
| Report code:                       | 9111                                               | Vehicle height (cm): |            |
| Chassis number:                    | W0LPD8EC6C8099111                                  | Vehicle body type:   |            |
| Type of vehicle:                   | Luxury                                             | Traction:            | Front      |
| First int. reg.:                   | 29/06/2012                                         | Power(kw):           | 103        |
| First NL req.:                     | 29/06/2012                                         | Transmission         | Automatic  |
| Color:                             | Black <input checked="" type="checkbox"/> Metallic | Number of gears      | 6          |
| Weight (kg)(kg):                   | 1503                                               | Displacement(cc):    | 1364       |
| Empty weight(kg):                  | 1403                                               | Number of cylinders: | 4          |
| Wheelbase (cm)(cm):                | 269                                                | Fuel type:           | Petrol     |
| Top speed (km/h):                  | 198                                                | Fuel tank capacity:  |            |
| Cons. in the city (l/100 km):      | 9.1                                                | EU category:         | Euro 5     |
| Cons. outside the city (l/100 km): | 5.4                                                | Energy label:        | B          |
| Average consumption (l/100 km):    | 6.8                                                | NL Tax Rate %:       |            |
| Acceleration (s):                  | 10.8                                               | CO2 (g/km):          | 159        |
| Cargo space (l):                   | 1503                                               | Nb. of Axles:        | 2          |
| Perm. max weight (kg):             | 2045                                               | APK date:            | 29/06/2025 |

## opties

|                                                                      |                                                                        |                                                                         |
|----------------------------------------------------------------------|------------------------------------------------------------------------|-------------------------------------------------------------------------|
| <input checked="" type="checkbox"/> Alloy wheels                     | <input checked="" type="checkbox"/> Roof rail (black)                  | <input checked="" type="checkbox"/> Bluetooth car kit                   |
| <input checked="" type="checkbox"/> Daytime running lights           | <input checked="" type="checkbox"/> Metallic finish                    | <input checked="" type="checkbox"/> Radio                               |
| <input checked="" type="checkbox"/> Licht Sensor                     | <input checked="" type="checkbox"/> Halogen headlights                 | <input checked="" type="checkbox"/> Cruise control                      |
| <input checked="" type="checkbox"/> Towing hook                      | <input checked="" type="checkbox"/> Exterior mirrors in car body color | <input checked="" type="checkbox"/> Airconditioning                     |
| <input checked="" type="checkbox"/> Anti-lock braking system         | <input checked="" type="checkbox"/> Rain sensor                        | <input checked="" type="checkbox"/> Climate control                     |
| <input checked="" type="checkbox"/> ABS                              | <input checked="" type="checkbox"/> Rear wiper                         | <input checked="" type="checkbox"/> Climate control (analog)            |
| <input checked="" type="checkbox"/> Airbag(s)                        | <input checked="" type="checkbox"/> Rear parking sensors               | <input checked="" type="checkbox"/> Climate control (digital)           |
| <input checked="" type="checkbox"/> Audio                            | <input checked="" type="checkbox"/> Towbar with fixed ball             | <input checked="" type="checkbox"/> Climate control (L/R separated)     |
| <input checked="" type="checkbox"/> Central locking system           | <input checked="" type="checkbox"/> Rear-seat folding (equal parts)    | <input checked="" type="checkbox"/> Large screen navigation             |
| <input checked="" type="checkbox"/> Fog lamps                        | <input checked="" type="checkbox"/> Rear-seat folding (unequal parts)  | <input checked="" type="checkbox"/> Electrically operated front windows |
| <input checked="" type="checkbox"/> Start/stop system                | <input checked="" type="checkbox"/> Luggage cover                      | <input checked="" type="checkbox"/> Electrically adjustable mirrors     |
| <input checked="" type="checkbox"/> Power steering                   | <input checked="" type="checkbox"/> Bluetooth streaming                | <input checked="" type="checkbox"/> Audio control on the steering wheel |
| <input checked="" type="checkbox"/> Front seats adjustable in height | <input checked="" type="checkbox"/> CD changer                         | <input checked="" type="checkbox"/> Leather steering wheel              |
| <input checked="" type="checkbox"/> Multifunctional steering wheel   | <input checked="" type="checkbox"/> Radio/CD player                    |                                                                         |
| <input checked="" type="checkbox"/> Remote central locking           | <input checked="" type="checkbox"/> Radio/CD/MP3 player                |                                                                         |

## Tires

| Tire position:   | Tire type:  | Wheel type: | Tire size: | Tire brand: | Tire profile depth (mm): |
|------------------|-------------|-------------|------------|-------------|--------------------------|
| Tire left front  | All weather | Alloy       | 215/50 R17 | Hifly       | 6                        |
| Tire left rear   | All weather | Alloy       | 215/50 R17 | Vredestein  | 7                        |
| Tire right front | All weather | Alloy       | 215/50 R17 | Hifly       | 6                        |
| Tire right rear  | All weather | Alloy       | 215/50 R17 | Vredestein  | 7                        |

## Additional information

|                   |                 |                                     |                                              |                                                                      |
|-------------------|-----------------|-------------------------------------|----------------------------------------------|----------------------------------------------------------------------|
| No. of keys:      | 2               | <input type="checkbox"/> Luxury key | <input type="checkbox"/> Instruction booklet | <input checked="" type="checkbox"/> Airco works                      |
| Interior color:   | Black           | Maintenance booklet:                | (serviceboekje (papier))                     | <input checked="" type="checkbox"/> Odorless                         |
| Upholstery:       | Half stof/leder |                                     |                                              | <input checked="" type="checkbox"/> Clean inside (Interior is clean) |
| No. of seats:     | 5               | Stamp date:                         | 28/05/2024                                   | <input checked="" type="checkbox"/> Display ok                       |
| No. of headrests: | 5               | Last turn mileage(km):              | 186234                                       | <input checked="" type="checkbox"/> Vehicle special usage (None)     |


## Cleaning

- ☒ Clean inside (Interior is clean)


☒ Clean outside (Cleaning)

## Damages


⊕ Not acceptable



Front left screen - Dent



Front bumper - Break




Bonnet - Paint repair



Front left door - Paint repair




Rear left door - Paint repair



Rear left screen - Dent



Rear bumper - Scratch



Left C- column - Bird droppings



Rear right door - Dent



Aircopump Defect - Storing Airbag Door Defecte Gordel



Bestuurderstoel beschadigd+Versnellingspook beschadigd



Bestuurderstoel beschadigd+Versnellingspook beschadigd

## Damages

⊕ Acceptable



