



# OPEL Corsa

## Corsa 1.4 Turbo (ecoFLEX) Start/Stop

VIN NO W0V0XEP68J4261812  
Registration Number 68J4261812



MOT Date

2026-12-01

Last Service

2024-01-23

Number of Owners

3

Last Service Mileage

64897

Number of Keys

3

First Registration Date

2018-05-24

Odometer Reading

79473 km

Country First Registered

Germany

### Inspection Report Summary

|                         |                            |                |                 |
|-------------------------|----------------------------|----------------|-----------------|
| Customer                | BCA Online                 | Report Number  | P20250605132423 |
| Inspection Date / Place | 2025-06-05 / BCA Oberndorf | Cosmetic Grade | 2               |


### Vehicle Summary

|                    |         |                        |        |
|--------------------|---------|------------------------|--------|
| Vehicle Condition  | Runner  | VAT Type               | Margin |
| Fuel Type          | Petrol  | Road Worthy            | Yes    |
| Colour             | White   | Engine Size (cc)       | 1364   |
| Engine Size        | 1.4     | No of Doors            | 5      |
| Body Type          | Sedan   | Drive Train            | Front  |
| Seat Colour        |         | No of Seats            | 5      |
| Seat Covering Name | Schwarz | Seat Covering          | Cloth  |
| Charging Cables    |         | NEDC CO2 Rating (q/km) | 125    |
| Gearbox Type       | Manual  |                        |        |

### Vehicle History & Documents

|                        |         |                      |    |
|------------------------|---------|----------------------|----|
| Service Book Available | Present | Next Service Mileage | km |
| Previous Usage         |         | Imported             | No |
| Manufacturer Warrenty  |         |                      |    |







Equipment

|                   |                               |                               |                          |
|-------------------|-------------------------------|-------------------------------|--------------------------|
| USB Socket        | Anti-lock braking             | Cruise control                | Remote central locking   |
| Stability control | CD Player                     | Leather steering wheel        | Rear parking sensors     |
| Airbag Status     | Bluetooth telephone interface | Remote adjusting wing mirrors | Split folding rear seats |
| Xenon headlamps   | Central locking               | Radio                         |                          |


Equipment Details

|                  |     |              |       |
|------------------|-----|--------------|-------|
| Air Conditioning | Yes | Seat Heating | Front |
|------------------|-----|--------------|-------|

Wheels & Tyres

|                        |   |                       |   |
|------------------------|---|-----------------------|---|
| Right Front Tyre Depth | 7 | Left Front Tyre Depth | 7 |
| Right Rear Tyre Depth  | 8 | Left Rear Tyre Depth  | 8 |

 Schäden


6/10 - Report Number P20250605132423



1. Anomalyon Element -



2. Blade/spoiler / Front Bodywork / Breakage -



3. Bumper / Front Paint / Scratch / Scuff -



4. Rocker Panel / Center Left Bodywork / Dent / Dent -




5. Door / Back Left Bodywork / Dent / Dent -



6. Door Edge / Back Left Bodywork / Dent / Dent -



7. Pillar / Front Left  
Bodywork / Dent / Dent -



8. Bumper / Back  
Paint / Scratch / Line -

## Mechanical Condition

### Control Lights

|                      |   |                                              |   |
|----------------------|---|----------------------------------------------|---|
| Display Defect       | ✓ | Service Light                                | ✓ |
| ABS Warning Light    | ✓ | ESP Fault/Traction Control Malfunction Light | ✓ |
| Airbag Warning Light | ✓ | Oil Pressure Warning Light                   | ✓ |
| Brake Warning Light  | ✓ | Power Steering Warning Light                 | ✓ |
| Alternator / Battery | ✓ | No Dashboard Lights                          | ✓ |

### Equipments Test

|                                       |   |                               |   |
|---------------------------------------|---|-------------------------------|---|
| Central Locking                       | ✓ | Main & Spare Keys Functioning | ✓ |
| Electric Windows                      | ✓ | Audio Equipment               | ✓ |
| Parking Sensors / Cameras Functioning | ✓ | AC / Heating System           | ✓ |
| Other Equipments                      | ✓ |                               |   |

### Engine

|                     |   |                     |   |
|---------------------|---|---------------------|---|
| Engine Status / EML | ✓ | Engine Leak Visible | ✓ |
| Engine Starts       | ✓ |                     |   |

### Gearbox

|          |   |
|----------|---|
| Gear Box | ✓ |
|----------|---|

### Levels

|              |   |               |   |
|--------------|---|---------------|---|
| Brakes Fluid | ✓ | Coolant Fluid | ✓ |
|--------------|---|---------------|---|

Test Drive Inspection

| Steering Wheel                                                                                       |   |                                               |   |
|------------------------------------------------------------------------------------------------------|---|-----------------------------------------------|---|
| Steering   Noise / Anomaly                                                                           |   | ✓                                             |   |
| Engine                                                                                               |   |                                               |   |
| Engine Noise                                                                                         | ✓ | The Gears Scratch / Skip / Abnormal Operation | ✓ |
| Fume Quantity                                                                                        | ✓ | Power Loss                                    | ✓ |
| Clutch                                                                                               |   |                                               |   |
| Clutch Functioning                                                                                   |   | ✓                                             |   |
| Brake                                                                                                |   |                                               |   |
| Brake System Anomaly                                                                                 |   | ✓                                             |   |
| General                                                                                              |   |                                               |   |
| Test Driven Status                                                                                   |   | Not Performed                                 |   |
| ✓ <i>No troubles detected, good condition or correct tests, according to vehicle age and mileage</i> |   |                                               |   |
| ! <i>Damages or malfunction detected that requires repairs by the buyer</i>                          |   |                                               |   |
| NA <i>Not applicable</i>                                                                             |   |                                               |   |
| = <i>Not tested</i>                                                                                  |   |                                               |   |

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description.

[User Guide](#)