


Vehicle details

VIN	W0V7D9ED2 L4383414	Brand	OPEL	Maintenance date	-
Licence Plate	J0-21-VD	Model	Crossland X 1.2 Turbo S:S 81Kw ACTI 5d Edition 202	Maintenance mileage	-
Registration date	28/10/2020	Year	2020	Exterior Color	Blue Metallic
Odometer	128 182 km	Engine size	1199	interior Color	Grey
Fuel	Petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Manual	CO2	-
Doors	5	Gears	6		

Inspection Details

Inspection date	29/07/2025	Inspection loc.	Dekra Ayvens		
-----------------	------------	-----------------	--------------	--	--



Generic equipment

Manual air-conditioning	✓
Cruise control	✓
Alloy wheel rims	✓
Metallic paint	✓
Central locking	✓
Electric windows	✓
Park Distance Control	✓
Audio System	✓


Removable element

Spare wheel (wheel & tyre)	✓
Rear parcel shelf	✓

Technical Document

User manual	✓
Warranty booklet	✓
Key	✓
Remote key	✓

Tyres

Michelin 195/60/16 Summer 6.0 mm		Michelin 195/60/16 Summer 6.0 mm	
Michelin 195/60/16 Summer 6.0 mm		Michelin 195/60/16 Summer 6.0 mm	

Exterior

1



Part	Wing
Position	Front left
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Smart Repair

2



Part	Wing
Position	Back right
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Smart Repair

3



Part	Door
Position	Front right
Damages	Dent & Chips
Severity	Diameter (mm) > 20
Repair mode	Repair

4



Part	Bonnet
Position	Front
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Smart Repair

5



Part	Roof
Position	-
Damages	Chemical deposit
Severity	Diameter (mm) > 20
Repair mode	Lumpsum repair