

Vehicle details

VIN	W0V7D9ED4 L4375833	Brand	OPEL	Maintenance date	-
Licence Plate	J2-09-RN	Model	Crossland X 1.2 Turbo S:S 81Kw ACTI 5d Edition 202	Maintenance mileage	-
Registration date	30/09/2020	Year	2020	Exterior Color	White Solid
Odometer	49 812 km	Engine size	1199	interior Color	Black
Fuel	Petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Manual	CO2	-
Doors	5	Gears	6		

Inspection Details

Inspection date	07/10/2025	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
Alloy wheel rims	✓
Central locking	✓
Electric windows	✓
Side rails	✓
Park Distance Control	✓
Audio System	✓
Led lighting	✓

Removable element


Spare wheel (wheel & tyre)	✓
Rear parcel shelf	✓

Technical Document

User manual	✓
Warranty booklet	✓
Key	✓
Remote key	✓

Tyres

Bridgestone 195/60/16 Summer 6.0 mm



Bridgestone 195/60/16 Summer 6.0 mm



Bridgestone 195/60/16 Summer 4.5 mm

Bridgestone 195/60/16 Summer 4.5 mm

Exterior

2



Part	Bumper
Position	Back
Damages	Scratched
Severity	-
Repair mode	Repair

3



Part	Roof
Position	-
Damages	Chemical deposit
Severity	-
Repair mode	Lumpsum repair

4



Part	Wing
Position	Front right
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Smart Repair

Interior damage

1



Part	Fabric seat
Position	Front
Damages	Stained/dirty
Severity	-
Repair mode	Cleaning