


Vehicle details

VIN	W0V7D9ED5 L4292511	Brand	OPEL	Maintenance date	-
Licence Plate	J7-14-LH	Model	Crossland X 1.2 Turbo S:S 81Kw ACTI 5d Edition 202	Maintenance mileage	-
Registration date	03/09/2020	Year	2020	Exterior Color	Grey Metallic
Odometer	71 740 km	Engine size	1199	interior Color	Black
Fuel	Petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Manual	CO2	-
Doors	5	Gears	6		

Inspection Details

Inspection date	12/09/2025	Inspection loc.	Ayvens Veghel
-----------------	------------	-----------------	---------------



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
GPS system	✓
Alloy wheel rims	✓
Metallic paint	✓
Central locking	✓
Electric windows	✓
Side rails	✓
Park Distance Control	✓
Audio System	✓
Led lighting	✓

Removable element

Spare wheel (wheel & tyre)	✓
Rear parcel shelf	✓

Technical Document

User manual	✓
Warranty booklet	✓
Key	✓
Remote key	✓
Sat Nav CD ROM Software	✓

Tyres

Bridgestone 195/60/16 Summer 7.0 mm		Bridgestone 195/60/16 Summer 7.0 mm		
Bridgestone 195/60/16 Summer 4.0 mm		Bridgestone 195/60/16 Summer 4.0 mm		

Exterior

3


Part	Wing
Position	Back left
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Smart Repair

4


Part	Tailgate / Boot door
Position	-
Damages	Chemical deposit
Severity	-
Repair mode	Lumpsum repair

5


Part	Wing
Position	Back right
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Repair

6


Part	Bonnet
Position	-
Damages	Chemical deposit
Severity	-
Repair mode	Lumpsum repair

7


Part	Windscreen
Position	-
Damages	Stone impact
Severity	-
Repair mode	For info

8


Part	Roof wind deflector
Position	-
Damages	Chemical deposit
Severity	-
Repair mode	Lumpsum repair

Interior damage

1


Part	Interior cleaning
Position	Front left
Damages	Stained/dirty
Severity	-
Repair mode	Cleaning

2


Part	Interior cleaning
Position	Back
Damages	Stained/dirty
Severity	-
Repair mode	Cleaning