

MAINTENANCE HISTORY

Generation date: 2025/10/15

Plate Number **J1-34-RN**
 Make **OPEL**
 Model **Crossland X**
 Vehicle Description **1.2 Turbo S;S 81Kw ACTI 5d Edition 2020 APL 5d**

DATE	MILEAGE	TYPE	DESCRIPTION	SUPPLIER
2025/08/17	0 KM	damage	<ul style="list-style-type: none"> Linkerzijde Deur LV Deur LA tegen obstakel ger. 	<ul style="list-style-type: none"> Keuze MLA niet repareren, ,
2022/03/04	0 KM	damage	<ul style="list-style-type: none"> Linkerzijde Deur LA div.met mog.verh.WBF 	<ul style="list-style-type: none"> Schadenet Broekhuis Zaandam, ,
2024/07/16	40528 KM	repair	<ul style="list-style-type: none"> APK icm beurt - NVT - Uitvoeren Bandvervanging - NVT - Uitvoeren Opel OH Klein - NVT - Uitvoeren 	<ul style="list-style-type: none"> James Auto Service Van der Molen, , James Auto Service Van der Molen, , James Auto Service Van der Molen, ,
2022/10/05	20346 KM	repair	<ul style="list-style-type: none"> Opel OH Klein - NVT - Uitvoeren Int luchtfilter - versleten - Vervangen 	<ul style="list-style-type: none"> Profile Car;Tyreserv. John van der, Molen, Profile Car;Tyreserv. John van der, Molen,