


Vehicle details

VIN	W0V7D9ED9 K4419906	Brand	OPEL	Maintenance date	-
Licence Plate	ZR-82-0J	Model	Crossland X 1.2 Turbo S;S ActieAuto auto 5d 120 Ja	Maintenance mileage	-
Registration date	18/07/2019	Year	2019	Exterior Color	Blue Solid
Odometer	86 339 km	Engine size	1199	interior Color	Grey
Fuel	Petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Automatic	CO2	-
Doors	5	Gears	-		

Inspection Details

Inspection date	07/08/2025	Inspection loc.	Ayvens Veghel
-----------------	------------	-----------------	---------------



Generic equipment


Manual air-conditioning	✓
Cruise control	✓
Alloy wheel rims	✓
Central locking	✓
Electric windows	✓
Audio System	✓

Removable element

Spare wheel (wheel & tyre)	✓
Rear parcel shelf	✓

Technical Document

Tyres

Bridgestone 195/60/16 Summer 6.5 mm		Bridgestone 195/60/16 Summer 6.5 mm	
Bridgestone 195/60/16 Summer 6.0 mm		Bridgestone 195/60/16 Summer 6.0 mm	

Exterior

2



●●

Part	Door
Position	Back left
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Smart Repair

5



●●

Part	Door
Position	Back right
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Smart Repair

6



●●

Part	Exterior door mirror shell
Position	Front right
Damages	Scratched
Severity	Length (cm) > 10
Repair mode	Repair

8



●●●

Part	Bonnet
Position	-
Damages	Dent & Chips
Severity	Diameter (mm) > 20
Repair mode	Repair

9



●●

Part	Roof post A/B/C
Position	Left
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Smart Repair

10




●●

Part	Wing
Position	Front right
Damages	Dent & Chips
Severity	Diameter (mm) > 20
Repair mode	Repair

Interior damage

1



●●

Part	Interior cleaning
Position	Front
Damages	Stained/dirty
Severity	-
Repair mode	Cleaning

3



●●●

Part	Interior cleaning
Position	Back
Damages	Stained/dirty
Severity	-
Repair mode	Cleaning

4



●●●

Part	Interior tailgate lining
Position	Down
Damages	Scratched
Severity	-
Repair mode	Replace

Others

7



Part	Damage appraisal
Position	-
Damages	Stone impact
Severity	-
Repair mode	For info