



Vehicle details

VIN	W0V7D9EDX L4364982	Brand	OPEL	Maintenance date	-
Licence Plate	J2-06-RN	Model	Crossland X 1.2 Turbo S:S 81Kw ACTI 5d Edition 202	Maintenance mileage	-
Registration date	30/09/2020	Year	2020	Exterior Color	Blue Metallic
Odometer	99 351 km	Engine size	1199	interior Color	Black
Fuel	Petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Manual	CO2	-
Doors	5	Gears	6		

Inspection Details

Inspection date	02/10/2025	Inspection loc.	Dekra Ayvens		
					
					
					
					

Generic equipment

Manual air-conditioning	✓
Cruise control	✓
GPS system	✓
Alloy wheel rims	✓
Tow	✓
Metallic paint	✓
Central locking	✓
Electric windows	✓
Park Distance Control	✓
Audio System	✓
Led lighting	✓

Removable element

Spare wheel (wheel & tyre)	✓
Rear parcel shelf	✓

Technical Document

User manual	✓
Warranty booklet	✓
Key	✓
Remote key	✓
Sat Nav CD ROM Software	✓

Tyres

Continental 195/55/16 Summer 6.5 mm		Continental 195/55/16 Summer 6.0 mm	
Continental 195/55/16 Summer 6.0 mm		Continental 195/55/16 Summer 6.0 mm	

Exterior

1


Part	Wing
Position	Front left
Damages	Dented
Severity	Number > 2
Repair mode	Smart Repair

2


Part	Alloy wheel 16"
Position	Front left
Damages	Scratched
Severity	-
Repair mode	Lumpsum repair

3



Part	Wing
Position	Back left
Damages	Dented
Severity	Number > 2
Repair mode	Smart Repair

4


Part	Bumper moulding
Position	Back
Damages	Scratched
Severity	Length (cm) > 10
Repair mode	Repair

5


Part	Door
Position	Back right
Damages	Dented
Severity	Number > 2
Repair mode	Smart Repair

6


Part	Alloy wheel 16"
Position	Front right
Damages	Scratched
Severity	-
Repair mode	Lumpsum repair

7


Part	Bumper
Position	Front
Damages	Scratched
Severity	Length (cm) > 10
Repair mode	Repair

8


Part	Roof
Position	-
Damages	Chemical deposit
Severity	-
Repair mode	Lumpsum repair

9


Part	Exterior door mirror shell
Position	Front left
Damages	Scratched
Severity	Length (cm) > 10
Repair mode	Repair

10


Part	Exterior door mirror shell
Position	Front right
Damages	Scratched
Severity	Length (cm) > 10
Repair mode	Repair