

Vehicle details

VIN	W0V7D9EE8 K4438939	Brand	OPEL	Maintenance date	-
Licence Plate	ZS-56-0X	Model	Crossland X 1.2 60Kw ActieAuto 5d 120 Jaar Edition	Maintenance mileage	-
Registration date	02/08/2019	Year	2019	Exterior Color	Blue Metallic
Odometer	24 491 km	Engine size	1199	interior Color	Grey
Fuel	Petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Manual	CO2	-
Doors	5	Gears	5		

Inspection Details

Inspection date	24/01/2025	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



Generic equipment

Manual air-conditioning	✓
Cruise control	✓
Alloy wheel rims	✓
Metallic paint	✓
Central locking	✓
Electric windows	✓
Park Distance Control	✓
Audio System	✓

Removable element

Spare wheel (wheel & tyre)	✓
Load cover	✓

Technical Document

User manual	✓
Warranty booklet	✓
Key	✓
Remote key	✓

Tyres

Bridgestone 195/60/16 Summer 5.0 mm		Bridgestone 195/60/16 Summer 5.0 mm	
Bridgestone 195/60/16 Summer 6.0 mm		Bridgestone 195/60/16 Summer 6.0 mm	

Exterior

1		Part	Wing	2		Part	Wing moulding
		Position	Back left			Position	Back left
		Damages	Scratched			Damages	Scratched
		Severity	Length (cm) > 10			Severity	Length (cm) > 10
		Repair mode	Repair			Repair mode	Repair

3

Part	Bumper
Position	Back left
Damages	Scratched
Severity	Length (cm) > 10
Repair mode	Repair

4

Part	Wing
Position	Back right
Damages	Scratched
Severity	Length (cm) > 10
Repair mode	Repair

5

Part	Door
Position	Back right
Damages	Dent & Chips
Severity	Diameter (mm) > 20
Repair mode	Repair

6

Part	Door
Position	Front right
Damages	Scratched
Severity	Length (cm) > 10
Repair mode	Repair

7

Part	Bonnet
Position	-
Damages	Dent & Chips
Severity	Diameter (mm) > 20
Repair mode	Repair

8

Part	Roof
Position	-
Damages	Chemical deposit
Severity	-
Repair mode	Lumpsum repair