

Vehicle details

VIN	W0V7H9ED0 K4428949	Brand	OPEL	Maintenance date	-
Licence Plate	ZV-34-1P	Model	Crossland X 1.2 Turbo S;S 81kW ActieAuto 5d Innova	Maintenance mileage	-
Registration date	17/08/2019	Year	2019	Exterior Color	White Solid
Odometer	91 296 km	Engine size	1199	interior Color	Grey
Fuel	Petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Manual	CO2	-
Doors	5	Gears	6		

Inspection Details

Inspection date	15/09/2025	Inspection loc.	Ayvens Veghel
-----------------	------------	-----------------	---------------



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
GPS system	✓
Alloy wheel rims	✓
Central locking	✓
Electric windows	✓
Side rails	✓
Park Distance Control	✓
Audio System	✓

Removable element


Spare wheel (wheel & tyre)	✓
Rear parcel shelf	✓

Technical Document

User manual	✓
Warranty booklet	✓
Spare key	✓
Remote key	✓
Sat Nav CD ROM Software	✓

Tyres

Hankook 195/60/16 Summer 6.5 mm



Hankook 195/60/16 Summer 6.0 mm



Hankook 195/60/16 Summer 6.5 mm

Hankook 195/60/16 Summer 6.5 mm

Exterior

1



●●●●●

Part	Roof
Position	-
Damages	Chemical deposit
Severity	-
Repair mode	Lumpsum repair

6



●●●

Part	Unpainted bumper
Position	Back
Damages	Scratched
Severity	Length (cm) > 10
Repair mode	Repair

7



●●

Part	Tailgate / Boot door
Position	-
Damages	Chemical deposit
Severity	-
Repair mode	Lumpsum repair

8



●●

Part	Wing
Position	Back right
Damages	Dented
Severity	Number > 2
Repair mode	Smart Repair

11



●●●

Part	Roof post A/B/C
Position	Right
Damages	Chemical deposit
Severity	-
Repair mode	Lumpsum repair

Interior damage

2



Part	Interior tailgate lining
Position	Up
Damages	Scratched
Severity	-
Repair mode	Replace

3



Part	Interior tailgate lining
Position	Left
Damages	Scratched
Severity	-
Repair mode	Replace

4



Part	Interior tailgate lining
Position	Right
Damages	Scratched
Severity	-
Repair mode	Replace

5



Part	Interior tailgate lining
Position	Down
Damages	Scratched
Severity	-
Repair mode	Replace

9



Part	Interior cleaning
Position	Back
Damages	Stained/dirty
Severity	-
Repair mode	Cleaning

10



Part	Interior cleaning
Position	Front right
Damages	Stained/dirty
Severity	-
Repair mode	Cleaning