


Vehicle details

VIN	W0V7H9ED8 K4434336	Brand	OPEL	Maintenance date	-
Licence Plate	ZS-47-7R	Model	Crossland X 1.2 Turbo S;S 81kW ActieAuto 5d Innova	Maintenance mileage	-
Registration date	30/07/2019	Year	2019	Exterior Color	Blue Metallic
Odometer	54 387 km	Engine size	1199	interior Color	Black
Fuel	Petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Manual	CO2	-
Doors	5	Gears	6		

Inspection Details

Inspection date	29/09/2025	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
GPS system	✓
Alloy wheel rims	✓
Metallic paint	✓
Central locking	✓
Electric windows	✓
Mixed upholstery	✓
Side rails	✓
Park Distance Control	✓
Audio System	✓

Removable element

Spare wheel (wheel & tyre)	✓
Rear parcel shelf	✓

Technical Document

User manual	✓
Warranty booklet	✓
Spare key	✓
Remote key	✓
Sat Nav CD ROM Software	✓

Tyres

Hankook 195/60/16 Summer 7.0 mm		Hankook 195/60/16 Summer 7.0 mm		
Bridgestone 195/60/16 Summer 3.0 mm		Bridgestone 195/60/16 Summer 3.0 mm		

Exterior

1



Part	Step plate
Position	Front right
Damages	Dented
Severity	-
Repair mode	For info

2



Part	Door
Position	Front right
Damages	Chemical deposit
Severity	-
Repair mode	Lumpsum repair

3



Part	Bonnet
Position	-
Damages	Chemical deposit
Severity	-
Repair mode	Lumpsum repair