

## Vehicle details

|                   |                    |              |                                                   |                           |             |
|-------------------|--------------------|--------------|---------------------------------------------------|---------------------------|-------------|
| VIN               | W0V7H9ED8 L4383020 | Brand        | OPEL                                              | Maintenance date          | -           |
| Licence Plate     | J6-80-SK           | Model        | Crossland X 1.2 Turbo S;S 81kW ACT1 5d Innovation | Maintenance mileage       | -           |
| Registration date | 14/10/2020         | Year         | 2020                                              | Exterior Color            | White Solid |
| Odometer          | 68 310 km          | Engine size  | 1199                                              | interior Color            | Black       |
| Fuel              | Petrol             | Body Type    | -                                                 | Next technical inspection | -           |
| Seats             | -                  | Transmission | Manual                                            | CO2                       | -           |
| Doors             | 5                  | Gears        | 6                                                 |                           |             |

## Inspection Details

|                 |            |                 |              |
|-----------------|------------|-----------------|--------------|
| Inspection date | 15/10/2025 | Inspection loc. | Dekra Ayvens |
|-----------------|------------|-----------------|--------------|



## Generic equipment

|                            |   |
|----------------------------|---|
| Automated air-conditioning | ✓ |
| Cruise control             | ✓ |
| Alloy wheel rims           | ✓ |
| Central locking            | ✓ |
| Electric windows           | ✓ |
| Mixed upholstery           | ✓ |
| Side rails                 | ✓ |
| Park Distance Control      | ✓ |
| Audio System               | ✓ |
| Led lighting               | ✓ |

## Removable element

|                            |   |
|----------------------------|---|
| Spare wheel (wheel & tyre) | ✓ |
| Rear parcel shelf          | ✓ |

## Technical Document

|                  |   |
|------------------|---|
| User manual      | ✓ |
| Warranty booklet | ✓ |
| Key              | ✓ |
| Remote key       | ✓ |

## Tyres

|                                     |                                                                                     |                                     |                                                                                     |
|-------------------------------------|-------------------------------------------------------------------------------------|-------------------------------------|-------------------------------------------------------------------------------------|
| Bridgestone 195/60/16 Summer 3.0 mm |  | Bridgestone 195/60/16 Summer 3.0 mm |  |
| Bridgestone 195/60/16 Summer 3.5 mm |  | Bridgestone 195/60/16 Summer 4.0 mm |  |

## Exterior

1



|             |                  |
|-------------|------------------|
| Part        | Door             |
| Position    | Back left        |
| Damages     | Scratched        |
| Severity    | Length (cm) > 10 |
| Repair mode | Repair           |

2



|             |              |
|-------------|--------------|
| Part        | Door         |
| Position    | Back right   |
| Damages     | Dented       |
| Severity    | Number > 2   |
| Repair mode | Smart Repair |

3



|             |              |
|-------------|--------------|
| Part        | Door         |
| Position    | Front right  |
| Damages     | Dented       |
| Severity    | Number > 2   |
| Repair mode | Smart Repair |

4



|             |                  |
|-------------|------------------|
| Part        | Bumper           |
| Position    | Front            |
| Damages     | Scratched        |
| Severity    | Length (cm) > 10 |
| Repair mode | Repair           |

5



|             |                            |
|-------------|----------------------------|
| Part        | Exterior door mirror shell |
| Position    | Front right                |
| Damages     | Scratched                  |
| Severity    | Length (cm) > 10           |
| Repair mode | Repair                     |

6



|             |            |
|-------------|------------|
| Part        | Headlight  |
| Position    | Front left |
| Damages     | Scratched  |
| Severity    | -          |
| Repair mode | For info   |

7



|             |                  |
|-------------|------------------|
| Part        | Wing             |
| Position    | Front right      |
| Damages     | Scratched        |
| Severity    | Length (cm) > 10 |
| Repair mode | Repair           |