



Opel Crossland: 2ASG642			
Vinnumber:	W0V7H9EN6M4203446	Versionname:	
First Registrationdate:	29/06/2021	Fiscalpower:	
Expertise Mileage:	80821	Power Kw:	81
Bodytype:		Body colour	Orange
Gearbox:	MAN 6 VIT	Type of rims (mounted)	Aluminium
Transmission:		Parking lot	3210
Fueltype:	Diesel		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		
Registration Certificate Home (BE)	No		
Options			
Number of keys total	2	Luggage cover	
Cruise Control		Front parking sensors	
Steering wheel multifunctional		Rear parking sensors	
Radio multimedia		Type of Tow bar	No Tow bar
Type of headlighting	Headlighting LED		
Type of GPS	GPS big screen color		
Type of Lining	Lining semi-artificial leather		
Type of climate control	Autom climate control		
Limited Technical Inspection			
Tyres			
Summer tyres:	195/60/16/89 H		
	Fr.L.	Bridgestone: 5 mm	Fr.R. Bridgestone: 5 mm
	Re.L.	Bridgestone: 5 mm	Re.R. Bridgestone: 5 mm
Tyre profile depth FL			5.0
Tyre profile depth FR			5.0
Tyre profile depth RL			5.0
Tyre profile depth RR			5.0
Tyre size FL			195/60 R 16 89 H
Tyre size FR			195/60 R 16 89 H
Tyre size RL			195/60 R 16 89 H
Tyre size RR			195/60 R 16 89 H
Tyre type FL			Summer
Tyre type FR			Summer
Tyre type RL			Summer
Tyre type RR			Summer
Tyre make FL			255
Tyre make FR			255
Tyre make RL			255
Tyre make RR			255
Assistance equipment			
Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		
Total cost ex VAT			958,28
Interior, Worn, Acceptable			0,00



Seat cover FR, Stain, Cleaning

28,43



Bonnet, Chemical polution, Polish

0,00



Bumper F, Scratch(es), Spot repair

144,58



Alloy rim FL, Scratch(es), Acceptable

0,00



Door FL, Dent(s), Acceptable

0,00



Boot carpet, Scratch(es), Acceptable

0,00



Internal boot lining R, Scratch(es), Acceptable

0,00



Internal boot lining L, Scratch(es), Acceptable

0,00



Rear window, Scratch(es), Replace

497,90





Rear spoiler, Chemical polution, Repair and paint (complete)	157,71
--	--------



Alloy rim FR, Scratch(es), Repair and paint (complete)	129,66
--	--------



Step R, Scratch(es), Acceptable	0,00
---------------------------------	------



Roof, Chemical polution, Polish	0,00
---------------------------------	------

