



Opel Astra (UKL): 1WLD196

Vinnumber:	W0VBD6EN5KG363804	Versionname:	Astra Edition 1.6CDTi EcoTEC Start/Stop 110pk/cv
First Registrationdate:	1/07/2019	Fiscalpower:	5p
Expertise Mileage:	132905	Power Kw:	81
Bodytype:		Type of rims (mounted)	Steel
Gearbox:	MAN 6 VIT		
Transmission:			
Fueltype:			
Maintenance	OK		
Maintenance	76%		
Battery functioning	Yes		
Type of rims (mounted)	Steel		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Luggage cover	
GPS		Type of Tow bar	No Tow bar
Type of Maintenance book	Digital maintenance		
Type of GPS storage	HD		

Tyres

205/55/16/91 W				
Summer tyres:	Fr.L.	Goodyear: 3 mm	Fr.R.	Goodyear: 4 mm
	Re.L.	Continental: 7 mm	Re.R.	Continental: 4 mm
Tyre profile depth FL				3.0
Tyre profile depth FR				4.0
Tyre profile depth RL				7.0
Tyre profile depth RR				4.0
Tyre size FL				205/55 R 16 91 W
Tyre size FR				205/55 R 16 91 W
Tyre size RL				205/55 R 16 91 V
Tyre size RR				205/55 R 16 91 V
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				259
Tyre make FR				259
Tyre make RL				256
Tyre make RR				256

Assistance equipment

Number of charging cables (normal)	0
Number of charging cables (rapid charge)	0

Seat cover R, Dirty, Cleaning



Door panel FR, Worn, Acceptable



Bonnet, Scratch(es), Acceptable



Door RL, Dent(s) and scratch(es), Repair and paint (complete)



Wing RL, Dent(s) and scratch(es), Repair and paint (complete)



Wheel cover RL, Scratch(es), Acceptable



Door FL, Scratch(es), Acceptable



Bumper R, Scratch(es), Spot repair



Bumper R, Dent(s) and scratch(es), Spot repair



Wing RR, Dent(s), Repair and paint (complete)



Door FR, Dent(s) and scratch(es), Acceptable



Wheel cover FR, Scratch(es), Replace



Bodywork, Not original part, Remove lettering

