


Vehicle details

VIN	W0VBD8EA3 K8070065	Brand	OPEL	Maintenance date	-
Licence Plate	G7-21-GD	Model	Astra Sports Tourer 1.0 Turbo 77kW S/S 120 Jaar Ed	Maintenance mileage	-
Registration date	23/09/2019	Year	2019	Exterior Color	Grey Metallic
Odometer	204 417 km	Engine size	999	interior Color	Grey
Fuel	Petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Manual	CO2	-
Doors	5	Gears	5		

Inspection Details

Inspection date	01/10/2025	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
GPS system	✓
Alloy wheel rims	✓
Tow	✓
Metallic paint	✓
Central locking	✓
Electric windows	✓
Side rails	✓
Park Distance Control	✓
Audio System	✓

Removable element


Spare wheel kit	✓
Load cover	✗

Technical Document

User manual	✓
Warranty booklet	✓
Spare key	✓
Remote key	✓
Sat Nav CD ROM Software	✓

Tyres

Pirelli 205/55/16 Summer 8.0 mm



Pirelli 205/55/16 Summer 8.5 mm



Pirelli 205/55/16 Summer 6.0 mm

Pirelli 205/55/16 Summer 6.0 mm

Exterior

1		Part Position Damages Severity Repair mode	Roof - Scratched Length (cm) > 10 Repair	2		Part Position Damages Severity Repair mode	Bonnet - Dent & Chips Diameter (mm) > 20 Repair
3		Part Position Damages Severity Repair mode	Bumper Front Scratched Length (cm) > 10 Repair	4		Part Position Damages Severity Repair mode	Alloy wheel 16" Front right Scratched - Lumpsum repair
5		Part Position Damages Severity Repair mode	Door Front right Dent & Chips Diameter (mm) > 20 Repair	6		Part Position Damages Severity Repair mode	Door Back right Dented Diameter (mm) > 20 Smart Repair
7		Part Position Damages Severity Repair mode	Wing Back right Dent & Chips Diameter (mm) > 20 Repair	8		Part Position Damages Severity Repair mode	Alloy wheel 16" Back right Scratched - Lumpsum repair
9		Part Position Damages Severity Repair mode	Bumper Back Dent & Chips Diameter (mm) > 20 Repair	10		Part Position Damages Severity Repair mode	Wing Back left Dent & Chips Diameter (mm) > 20 Repair
11		Part Position Damages Severity Repair mode	Sill Left Dented Diameter (mm) > 20 Repair	13		Part Position Damages Severity Repair mode	Roof post A/B/C Left Dent & Chips Diameter (mm) > 20 Repair
15		Part Position Damages Severity Repair mode	Door Back left Scratched Length (cm) > 10 Repair	16		Part Position Damages Severity Repair mode	Door Front left Scratched Length (cm) > 10 Repair

Interior damage

12



● ●

Part	Interior cleaning
Position	Back
Damages	Stained/dirty
Severity	-
Repair mode	Cleaning

14



●

Part	Load cover
Position	-
Damages	Missing
Severity	-
Repair mode	Replace