



OPEL ASTRA SPORTS TOURER: 1YQU967

Vinnumber:	W0VBD8ER8L8038378	Versionname:	1.2 Turbo 81kW S/S Edition
First Registrationdate:	9/11/2020	Fiscalpower:	
Expertise Mileage:	76433	Power Kw:	81
Bodytype:		Parking lot	1128
Gearbox:	Automatic	Type of rims (mounted)	Aluminium
Transmission:		Body colour	Black
Fueltype:	Petrol		
Certificate of Conformity	Yes		
Type of rims (mounted)	Aluminium		
Category	Passenger Car		
Registration Certificate Home (BE)	No		
Registration Certificate Car (BE)	Yes		

Options

Radio multimedia		Luggage cover	
Steering wheel multifunctional		Rear parking sensors	
Type of GPS	GPS big screen color	Type of Tow bar	No Tow bar
Cruise Control			
Type of climate control	Manual climate control		
Number of keys total	2		
Type of headlighting	Headlighting LED		
Type of Lining	Lining fabrics		

Limited Technical Inspection

Tyres

Tyre size RL	205/55 R 16 91 H
Tyre type FL	Winter
Tyre type RL	Winter
Tyre profile depth FR	4.0
Tyre profile depth RR	5.0
Tyre make FR	261
Tyre size FR	205/55 R 16 91 H
Tyre make RR	261
Tyre size RR	205/55 R 16 91 H

205/55/16/91 H			
Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Tyre profile depth FL	4.0
Tyre make FL	261
Tyre size FL	205/55 R 16 91 H
Tyre type FR	Winter
Tyre profile depth RL	5.0
Tyre type RR	Winter
Tyre make RL	261

Assistance equipment

Number of charging cables (normal)	0	Compressor	Yes
Number of charging cables (rapid charge)	0		
Repair kit	Yes		

Total cost ex VAT	677,90
--------------------------	---------------

Interior, Worn, Acceptable	0,00
-----------------------------------	-------------



Bumper spoiler F, Deformed / Strained, Smart repair 113,74



Windscreen, Stone chip(s), Acceptable 0,00



Bonnet, Chemical pollution, Polish 0,00




Door FL, Scratch(es), Repair and paint (complete) 434,50




Door RL, Scratch(es), Acceptable 0,00



Alloy rim RL, Scratch(es), Acceptable 0,00



Wing FL, Scratch(es), Acceptable 0,00



Rear window, Scratch(es), Replace 0,00



Tailgate / Boot, Scratch(es), Acceptable 0,00



Alloy rim RR, Scratch(es), Repair and paint (complete) 129,66



Wing RR, Scratch(es), Acceptable 0,00



Step R, Scratch(es), Polish 0,00



Wing RR, Repaired, Acceptable 0,00



Door RR, Repaired, Acceptable 0,00



Door FR, Repaired, Acceptable 0,00

