


Vehicle details

VIN	W0VBD8ERX M8017324	Brand	OPEL	Maintenance date	-
Licence Plate	L4-33-HB	Model	Astra Sports Tourer 1.2 turbo 81kW Edition 5d	Maintenance mileage	-
Registration date	25/05/2021	Year	2021	Exterior Color	White Solid
Odometer	122 400 km	Engine size	1199	interior Color	Grey
Fuel	Petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Manual	CO2	-
Doors	5	Gears	6		

Inspection Details

Inspection date	11/08/2025	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



Generic equipment

Manual air-conditioning	✓
Cruise control	✓
GPS system	✓
Alloy wheel rims	✓
Tow	✓
Central locking	✓
Electric windows	✓
Side rails	✓
Park Distance Control	✓
Audio System	✓
Led lighting	✓

Removable element

Spare wheel kit	✓
Load cover	✓

Technical Document

Spare key	✗
User manual	✓
Warranty booklet	✓
Sat Nav CD ROM Software	✓

Tyres

Michelin 205/55/16 Summer 5.5 mm	Michelin 205/55/16 Summer 5.0 mm
Continental 205/55/16 Summer 5.0 mm	Continental 205/55/16 Summer 4.5 mm

Exterior

2



●

●

Part	Bumper
Position	Front
Damages	Scratched
Severity	Length (cm) > 10
Repair mode	Repair

3



●

●

Part	Bumper
Position	Back
Damages	Scratched
Severity	Length (cm) > 10
Repair mode	Repair

4



●

●

●

Part	Alloy wheel 16"
Position	Back left
Damages	Scratched
Severity	-
Repair mode	Lumpsum repair

5



●

●

Part	Door
Position	Back left
Damages	Scratched
Severity	Length (cm) > 10
Repair mode	Repair

6



●

●

Part	Door
Position	Front left
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Smart Repair

7



●

●

Part	Step plate
Position	Front left
Damages	Dent & Chips
Severity	-
Repair mode	For info

Interior damage

1



Part	Spare key
Position	-
Damages	Missing
Severity	-
Repair mode	Replace