



OPEL ASTRA SPORTS TOURER: 2AEG088				
Vinnumber:	W0VBD8EU5M8011712	Versionname:	1.5 Turbo D 77kW S/S Edition	
First Registrationdate:	8/03/2021	Fiscalpower:		
Expertise Mileage:	164034	Power Kw:	77	
Bodytype:		Body colour	Grey	
Gearbox:	MAN 6 VIT	Type of rims (mounted)	Aluminium	
Transmission:		Parking lot	2614	
Fueltype:	Diesel			
Type of rims (mounted)	Aluminium			
Certificate of Conformity	Yes			
Category	Passenger Car			
Registration Certificate Car (BE)	Yes			
Options				
Number of keys total	2	Luggage cover		
Cruise Control		Front parking sensors		
Steering wheel multifunctional		Rear parking sensors		
Radio multimedia		Type of Tow bar	Tow bar removable	
Type of headlighting	Headlighting LED			
Type of GPS	GPS big screen color			
Type of Lining	Lining fabrics			
Type of climate control	Manual climate control			
Limited Technical Inspection				
Tyres				
Winter tyres:	205/55/16/92 H			
	Fr.L.	BF Goodrich: 5 mm	Fr.R.	BF Goodrich: 5 mm
	Re.L.	BF Goodrich: 5 mm	Re.R.	BF Goodrich: 5 mm
Tyre profile depth FL				5.0
Tyre profile depth FR				5.0
Tyre profile depth RL				5.0
Tyre profile depth RR				5.0
Tyre size FL				205/55 R 16 92 H
Tyre size FR				205/55 R 16 92 H
Tyre size RL				205/55 R 16 92 H
Tyre size RR				205/55 R 16 92 H
Tyre type FL				Winter
Tyre type FR				Winter
Tyre type RL				Winter
Tyre type RR				Winter
Tyre make FL				2485
Tyre make FR				2485
Tyre make RL				2485
Tyre make RR				2485
Assistance equipment				
Repair kit	Yes	Compressor		Yes
Number of charging cables (normal)	0			
Number of charging cables (rapid charge)	0			
Total cost ex VAT				1545,48
Bumper F, Scratch(es), Repair and paint (complete)				289,07



Wing RL, Dent(s), Acceptable	0,00
------------------------------	------



Step L, Scratch(es), Repair and paint (complete)	157,71
--	--------



Alloy rim RL, Scratch(es), Repair and paint (complete)	129,66
--	--------



Wing RL, Dent(s) and scratch(es), Acceptable	0,00
--	------




Door RL, Scratch(es), Acceptable	0,00
----------------------------------	------



Door FL, Scratch(es), Acceptable	0,00
----------------------------------	------



Alloy rim FL, Scratch(es), Repair and paint (complete)	129,66
--	--------



Bumper R, Scratch(es), Repair and paint (complete)	289,07
--	--------



Tailgate / Boot, Scratch(es), Acceptable	0,00
--	------



Rear window, Scratch(es), Replace	0,00
-----------------------------------	------



Alloy rim FR, Scratch(es), Repair and paint (complete)

129,66



Door RR, Scratch(es), Acceptable

0,00



Wing RR, Dent(s), Repair and paint (complete)

420,65



Alloy rim RR, Scratch(es), Acceptable

0,00



Bodywork, Not original part, Remove lettering

0,00

