



Opel Astra: XZ639N

Vinnumber:	W0VBE6EA4KG353386	Versionname:	Astra 1.0 Turbo Ecoflex 77kW S/S Innovation
First Registrationdate:	19/04/2019	Fiscalpower:	
Expertise Mileage:	130235	Power Kw:	77
Bodytype:		Body colour:	Indigo Blue (S)
Gearbox:	MAN 5 VIT	Paint type:	Opaque
Transmission:	Front	Type of rims (mounted):	Aluminium
Fueltype:	Petrol	Parking lot:	1040
Number of seats:	5		
Type of rims (mounted):	Aluminium		
Maintenance needed:	No		

Options

Number of keys total	2	Telephone equipment
GPS		Lining semi-leather
Autom climate control		Central consol F
Windows electric F		Luggage cover
Radio multimedia		Front parking sensors
		Rear parking sensors

Degree of wear


	205/55/16/91 H			
Winter tyres:	Fr.L.	Dunlop: 4,8 mm	Fr.R.	Dunlop: 4,7 mm
	Re.L.	Pirelli: 7 mm	Re.R.	Pirelli: 6,6 mm
Tyre profile depth FL				4.8
Tyre profile depth FR				4.7
Tyre profile depth RL				7.0
Tyre profile depth RR				6.6
Tyre size FL				205/55 R 16 91 H
Tyre size FR				205/55 R 16 91 H
Tyre size RL				205/55 R 16 91 H
Tyre size RR				205/55 R 16 91 H
Tyre type FL				Winter
Tyre type FR				Winter
Tyre type RL				Winter
Tyre type RR				Winter
Tyre make FL				257
Tyre make FR				257
Tyre make RL				264
Tyre make RR				264

Assistance equipment


Number of charging cables (normal)	0
Number of charging cables (rapid charge)	0

Door FL, Dent(s) and scratch(es), Repair and paint (complete)





Door RL, Scratch(es), Repair and paint (complete)



Wing RL, Dent(s) and scratch(es), Repair and paint (complete)



Outer door handle RL, Scratch(es), Repair and paint (complete)



Outer door handle FL, Scratch(es), Repair and paint (complete)



Wing FL, Scratch(es), Polish



Outside rear-view mirror housing L, Scratch(es), Polish



Windscreen, Stone chip(s), Windscreen repair



Rearset, Dent(s), Repair and paint (complete)


Bonnet, Dent(s), Repair and paint (complete)



Bumper F, Dent(s) and scratch(es), Repair and paint (complete)



Door FR, Dent(s) and scratch(es), Repair and paint (complete)



Wing FR, Dent(s), Repair and paint (complete)



Wing RR, Dent(s) and scratch(es), Repair and paint (complete)





Door RR, Dent(s) and scratch(es), Repair and paint (complete)



Roof pillar R, Scratch(es), Polish



Outside rear-view mirror housing R, Scratch(es), Polish



Boot lid covering R, Scratch(es), Replace



Rear window, Scratch(es), Replace



Bumper R, Scratch(es), Repair and paint (complete)





Roof, Scratch(es), Polish

