


Vehicle details

VIN	W0VBE8ER4 N8028219	Brand	OPEL	Maintenance date	-
Licence Plate	N4-46-JF	Model	Astra Sports Tourer 1.2 turbo 81kW Design & Te	Maintenance mileage	-
Registration date	27/10/2021	Year	2021	Exterior Color	White Solid
Odometer	113 483 km	Engine size	1199	interior Color	Grey
Fuel	Petrol	Body Type	-	Next technical inspection	-
Seats	5	Transmission	Manual	CO2	-
Doors	5	Gears	-		

Inspection Details

Inspection date	09/09/2025	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
GPS system	✓
Alloy wheel rims	✓
Tow	✓
Central locking	✓
Electric windows	✓
Mixed upholstery	✓
Side rails	✓
Park Distance Control	✓
Audio System	✓
Led lighting	✓



Removable element

Spare wheel kit	✓
Load cover	✓

Technical Document

User manual	✓
Warranty booklet	✓
Spare key	✓
Remote key	✓
Sat Nav CD ROM Software	✓

Tyres

Pirelli 205/55/16 Summer 8.0 mm		Pirelli 205/55/16 Summer 8.0 mm	
Continental 205/55/16 Summer 6.5 mm		Continental 205/55/16 Summer 6.5 mm	

Exterior

1		Part Position Damages Severity Repair mode	Bumper Front Scratched Length (cm) > 10 Repair	2		Part Position Damages Severity Repair mode	Windscreen - Stone impact - For info
3		Part Position Damages Severity Repair mode	Alloy wheel 16" Front right Scratched - Lumpsum repair	4		Part Position Damages Severity Repair mode	Door Back right Dented Diameter (mm) > 20 Smart Repair
5		Part Position Damages Severity Repair mode	Wing Back right Dented Diameter (mm) > 20 Smart Repair	6		Part Position Damages Severity Repair mode	Bumper Back Scratched Length (cm) > 10 Repair
7		Part Position Damages Severity Repair mode	Wing Back left Dent & Chips Diameter (mm) > 20 Repair	8		Part Position Damages Severity Repair mode	Alloy wheel 16" Back left Scratched - Lumpsum repair
9		Part Position Damages Severity Repair mode	Door Back left Dent & Chips Diameter (mm) > 20 Repair	10		Part Position Damages Severity Repair mode	Alloy wheel 16" Front left Scratched - Lumpsum repair

Interior damage

11		Part Position Damages Severity Repair mode	Leather seat Front left Worn out - For info
----	---	--	---