


Vehicle details

VIN	W0VBE8ET8 M8010462	Brand	OPEL	Maintenance date	-
Licence Plate	K2-61-TZ	Model	Astra Sports Tourer 1.4 turbo 107kW auto Business	Maintenance mileage	-
Registration date	15/03/2021	Year	2021	Exterior Color	Grey Metallic
Odometer	104 932 km	Engine size	1350	interior Color	Grey
Fuel	Petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Automatic	CO2	-
Doors	5	Gears	-		

Inspection Details

Inspection date	05/06/2025	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
Leather	✓
GPS system	✓
Alloy wheel rims	✓
Automatic Gearbox	✓
Heating seats	✓
Electric seats	✓
Tow	✓
Metallic paint	✓
Central locking	✓
Electric windows	✓
Side rails	✓
Park Distance Control	✓
Audio System	✓
Lane Keeping Assist (LKA)	✓
Park Assist	✓

Removable element

Spare wheel kit	✓
Load cover	✓


Technical Document

User manual	✓
Warranty booklet	✓
Spare key	✓
Remote key	✓
Sat Nav CD ROM Software	✓

Tyres

Winter kit

Pirelli 225/45/17 Winter 8.2 mm



Pirelli 225/45/17 Winter 4.5 mm



Pirelli 225/45/17 Winter 6.0 mm

Pirelli 225/45/17 Winter 6.5 mm


Exterior

1



Part	Bumper
Position	Front
Damages	Scratched
Severity	Length (cm) > 10
Repair mode	Repair

2



Part	Alloy wheel 17"
Position	Front left
Damages	Scratched
Severity	-
Repair mode	Lumpsum repair

3



Part	Step plate
Position	Front left
Damages	Scratched
Severity	-
Repair mode	For info

4



Part	Door
Position	Back left
Damages	Scratched
Severity	Length (cm) > 10
Repair mode	Repair

5



Part	Wing
Position	Back left
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Smart Repair

6



Part	Alloy wheel 17"
Position	Back left
Damages	Scratched
Severity	-
Repair mode	Lumpsum repair

7



Part	Bumper
Position	Back
Damages	Scratched
Severity	Length (cm) > 10
Repair mode	Repair

8



Part	Alloy wheel 17"
Position	Back right
Damages	Scratched
Severity	-
Repair mode	Lumpsum repair

9



Part	Wing
Position	Back right
Damages	Dent & Chips
Severity	Diameter (mm) > 20
Repair mode	Repair

10



Part	Door
Position	Back right
Damages	Scratched
Severity	Length (cm) > 10
Repair mode	Repair

11



Part	Wing
Position	Front right
Damages	Dent & Chips
Severity	Diameter (mm) > 20
Repair mode	Repair

12



Part	Alloy wheel 17"
Position	Front right
Damages	Scratched
Severity	-
Repair mode	Lumpsum repair

Interior damage

13



Part	Interior cleaning
Position	Back
Damages	Stained/dirty
Severity	-
Repair mode	Cleaning