


Vehicle details

VIN	W0VBE8EV6 L8000254	Brand	OPEL	Maintenance date	-
Licence Plate	G4-54-SN	Model	Astra Sports Tourer 1.5 CDTI S/S 90kW Elegance	Maintenance mileage	-
Registration date	25/11/2019	Year	2019	Exterior Color	Silver Metallic
Odometer	181 608 km	Engine size	1496	interior Color	Grey
Fuel	Diesel	Body Type	-	Next technical inspection	-
Seats	5	Transmission	Manual	CO2	-
Doors	5	Gears	-		

Inspection Details

Inspection date	09/09/2025	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
GPS system	✓
Alloy wheel rims	✓
Heating seats	✓
Metallic paint	✓
Central locking	✓
Electric windows	✓
Mixed upholstery	✓
Side rails	✓
Park Distance Control	✓
Audio System	✓
Led lighting	✓


Removable element

Spare wheel kit	✓
Load cover	✓

Technical Document

User manual	✓
Warranty booklet	✓
Spare key	✓
Remote key	✓
Sat Nav CD ROM Software	✓

Tyres

Michelin 225/40/18 Summer 6.0 mm		Michelin 225/40/18 Summer 5.5 mm	
Michelin 225/40/18 Summer 7.0 mm		Michelin 225/40/18 Summer 7.0 mm	

Exterior

1



Part

Alloy wheel 18"

Position

Front right

Damages

Scratched

Severity

-

Repair mode

Lumpsum repair

2



Part

Alloy wheel 18"

Position

Back right

Damages

Scratched

Severity

-

Repair mode

Lumpsum repair

3



Part

Alloy wheel 18"

Position

Back left

Damages

Scratched

Severity

-

Repair mode

Lumpsum repair

4



Part

Alloy wheel 18"

Position

Front left

Damages

Scratched

Severity

-

Repair mode

Lumpsum repair

5



Part

Wing

Position

Back left

Damages

Dented

Severity

Diameter (mm) > 20

Repair mode

Smart Repair