


Vehicle details

VIN	W0VDD6E70 JC479704	Brand	OPEL	Maintenance date	-
Licence Plate	TP-57-8K	Model	Karl 1.0 Start/Stop ROCKS Online Edition 5d	Maintenance mileage	-
Registration date	25/09/2018	Year	2018	Exterior Color	Black Metallic
Odometer	24 050 km	Engine size	999	interior Color	Black
Fuel	Petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Manual	CO2	-
Doors	5	Gears	5		

Inspection Details

Inspection date	26/09/2025	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



Generic equipment

Manual air-conditioning	✓
Cruise control	✓
GPS system	✓
Alloy wheel rims	✓
Metallic paint	✓
Central locking	✓
Electric windows	✓
Side rails	✓
Audio System	✓

Removable element

Spare wheel (wheel & tyre)	✓
Rear parcel shelf	✗

Technical Document

User manual	✓
Warranty booklet	✓
Spare key	✓
Remote key	✓
Sat Nav CD ROM Software	✓

Tyres

Continental 185/55/15 Summer 6.0 mm



Continental 185/55/15 Summer 5.5 mm



Continental 185/55/15 Summer 6.0 mm

Continental 185/55/15 Summer 6.5 mm

Exterior

2



●●●

Part	Alloy wheel 15"
Position	Front left
Damages	Scratched
Severity	-
Repair mode	Lumpsum repair

3



●●●

Part	Door
Position	Front left
Damages	Dent & Chips
Severity	-
Repair mode	Repair

5



●●

Part	Dashboard and drawer
Position	-
Damages	Scratched
Severity	-
Repair mode	For info

6



●●●

Part	Door
Position	Back left
Damages	Dent & Chips
Severity	-
Repair mode	Repair

7



●●●●

Part	Step plate
Position	Back left
Damages	Dent & Chips
Severity	-
Repair mode	For info

8



●●

Part	Wing
Position	Back left
Damages	Chemical deposit
Severity	-
Repair mode	Lumpsum repair

10



●●●

Part	Step plate
Position	Back right
Damages	Dent & Chips
Severity	-
Repair mode	For info

11



●●●●●●●

Part	Door
Position	Back right
Damages	Dent & Chips
Severity	-
Repair mode	Repair

12



●●●●●●●●

Part	Door
Position	Front right
Damages	Dent & Chips
Severity	-
Repair mode	Repair

13



●●

Part	Alloy wheel 15"
Position	Front right
Damages	Scratched
Severity	-
Repair mode	Lumpsum repair

14



●●●

Part	Bumper
Position	Front
Damages	Scratched
Severity	-
Repair mode	Repair

15



●●●

Part	Bonnet
Position	-
Damages	Chemical deposit
Severity	-
Repair mode	Lumpsum repair

16



●●

Part	Bumper protection film
Position	Front
Damages	Broken
Severity	-
Repair mode	Replace

Interior damage

1



Part	Rear parcel shelf
Position	-
Damages	Missing
Severity	-
Repair mode	Replace

4



Part	Fabric seat
Position	Front
Damages	Stained/dirty
Severity	-
Repair mode	Cleaning

9



Part	Fabric head restraint
Position	Back right
Damages	Missing
Severity	-
Repair mode	Lumpsum replacement