

Vehicle details

VIN	W0VDD6E71 KC787398	Brand	OPEL	Maintenance date	-
Licence Plate	G8-12-GD	Model	Karl 1.0 Start/Stop 120 Jaar Edition 5d	Maintenance mileage	-
Registration date	28/09/2019	Year	2019	Exterior Color	White Solid
Odometer	59 350 km	Engine size	999	interior Color	Black
Fuel	Petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Manual	CO2	-
Doors	5	Gears	5		

Inspection Details

Inspection date	29/09/2025	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



Generic equipment

Manual air-conditioning	✓
Cruise control	✓
Central locking	✓
Electric windows	✓
Park Distance Control	✓
Audio System	✓


Removable element

Spare wheel (wheel & tyre)	✓
Rear parcel shelf	✓


Technical Document

User manual	✓
Warranty booklet	✓
Spare key	✓
Remote key	✓

Tyres



Exterior

3		Part	Wing	4		Part	Bumper
		Position	Front left			Position	Back
		Damages	Dented			Damages	Scratched
		Severity	Diameter (mm) > 20			Severity	Length (cm) > 10
		Repair mode	Smart Repair			Repair mode	Repair

9



Part	Bumper
Position	Front
Damages	Scratched
Severity	Length (cm) > 10
Repair mode	Repair

10



Part	Roof
Position	-
Damages	Chemical deposit
Severity	-
Repair mode	Lumpsum repair

Interior damage

1

Part	Interior cleaning
Position	Front
Damages	Stained/dirty
Severity	-
Repair mode	Cleaning

2

Part	Interior cleaning
Position	Back
Damages	Stained/dirty
Severity	-
Repair mode	Cleaning

5

Part	Interior tailgate lining
Position	Up
Damages	Scratched
Severity	-
Repair mode	Replace

6

Part	Interior tailgate lining
Position	Left
Damages	Scratched
Severity	-
Repair mode	Replace

7

Part	Interior tailgate lining
Position	Right
Damages	Scratched
Severity	-
Repair mode	Replace

8

Part	Interior tailgate lining
Position	Down
Damages	Scratched
Severity	-
Repair mode	Replace