

Vehicle details

VIN	W0VDD6E76 JC469582	Brand	OPEL	Maintenance date	-
Licence Plate	TS-22-3V	Model	Karl 1.0 Start/Stop 75pk ROCKS Online Edition	Maintenance mileage	-
Registration date	15/10/2018	Year	2018	Exterior Color	White Solid
Odometer	109 600 km	Engine size	999	interior Color	Grey
Fuel	Petrol	Body Type	-	Next technical inspection	-
Seats	5	Transmission	Manual	CO2	-
Doors	5	Gears	-		

Inspection Details

Inspection date	05/09/2025	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



Generic equipment

Manual air-conditioning	✓
Cruise control	✓
Alloy wheel rims	✓
Central locking	✓
Electric windows	✓
Park Distance Control	✓
Audio System	✓

Removable element

Spare wheel (wheel & tyre)	✓
Rear parcel shelf	✓

Technical Document

User manual	✓
Warranty booklet	✓
Spare key	✓
Remote key	✓

Tyres

Continental 185/55/15 Summer 5.0 mm		Continental 185/55/15 Summer 5.0 mm		Continental 185/55/15 Summer 9.0 mm
Continental 185/55/15 Summer 4.0 mm		Continental 185/55/15 Summer 4.0 mm		

Exterior

1		Part	Bonnet	2		Part	Spoiler
		Position	-			Position	Front
		Damages	Dent & Chips			Damages	Scratched
		Severity	-			Severity	-
		Repair mode	Repair			Repair mode	Repair

3



Part

Alloy wheel 15"

Position

Front left

Damages

Scratched

Severity

-

Repair mode

Lumpsum repair

4



Part

Roof post A/B/C

Position

Left

Damages

Dented

Severity

Diameter (mm) > 20

Repair mode

Smart Repair

5



Part

Roofrail

Position

Left

Damages

Not conform

Severity

-

Repair mode

For info

6



Part

Door

Position

Front left

Damages

Dent & Chips

Severity

-

Repair mode

Repair

7



Part

Door

Position

Back left

Damages

Dented


Severity

Number > 2

Repair mode

Smart Repair

8



Part

Alloy wheel 15"

Position

Back left

Damages

Scratched


Severity

-

Repair mode

Lumpsum repair

9



Part

Alloy wheel 15"

Position

Back right

Damages

Scratched

Severity

-

Repair mode

Lumpsum repair

10



Part

Door

Position

Back right

Damages

Dented

Severity

Number > 2

Repair mode

Smart Repair

11



Part

Door

Position

Front right

Damages

Dented

Severity

Number > 2

Repair mode

Smart Repair

12



Part

Alloy wheel 15"

Position

Front right

Damages

Scratched

Severity

-

Repair mode

Lumpsum repair