

Vehicle details

VIN	W0VDD6E78 JC475688	Brand	OPEL	Maintenance date	-
Licence Plate	TX-49-9J	Model	Karl 1.0 Start/Stop ROCKS Online Edition 5d	Maintenance mileage	-
Registration date	09/11/2018	Year	2018	Exterior Color	Black Metallic
Odometer	156 080 km	Engine size	999	interior Color	Grey
Fuel	Petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Manual	CO2	-
Doors	5	Gears	5		

Inspection Details

Inspection date	23/09/2025	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



Generic equipment

Manual air-conditioning	✓
Cruise control	✓
GPS system	✓
Alloy wheel rims	✓
Metallic paint	✓
Central locking	✓
Electric windows	✓
Side rails	✓
Park Distance Control	✓
Audio System	✓



Removable element

Spare wheel (wheel & tyre)	✓
Rear parcel shelf	✓

Technical Document

User manual	✓
Warranty booklet	✓
Spare key	✓
Remote key	✓
Sat Nav CD ROM Software	✓

Tyres

Michelin 185/55/15 Summer 5.0 mm		Michelin 185/55/15 Summer 5.0 mm	
Continental 185/55/15 Summer 6.0 mm		Continental 185/55/15 Summer 6.0 mm	

Exterior

1		Part: Door Position: Front left Damages: Dented Severity: Diameter (mm) > 20 Repair mode: Repair	4		Part: Wing Position: Back left Damages: Dent & Chips Severity: Diameter (mm) > 20 Repair mode: Repair
5		Part: Wing moulding Position: Back left Damages: Scratched Severity: Length (cm) > 10 Repair mode: Repair	7		Part: Door Position: Back right Damages: Dent & Chips Severity: Diameter (mm) > 20 Repair mode: Repair
8		Part: Door Position: Front right Damages: Dent & Chips Severity: Diameter (mm) > 20 Repair mode: Repair	9		Part: Alloy wheel 15" Position: Front right Damages: Scratched Severity: - Repair mode: Lumpsum repair
10		Part: Exterior door mirror shell Position: Right Damages: Scratched Severity: Length (cm) > 10 Repair mode: Repair	11		Part: Bonnet Position: - Damages: Dent & Chips Severity: Diameter (mm) > 20 Repair mode: Repair
12		Part: Roof Position: - Damages: Dented Severity: Diameter (mm) > 20 Repair mode: Smart Repair			

Interior damage

2		Part: Interior cleaning Position: Front Damages: Stained/dirty Severity: - Repair mode: Cleaning			
3		Part: Steering wheel Position: - Damages: Worn out Severity: - Repair mode: For info	6		Part: Interior cleaning Position: Back Damages: Stained/dirty Severity: - Repair mode: Cleaning