


Vehicle details

VIN	W0VDD6E7X KC807261	Brand	OPEL	Maintenance date	-
Licence Plate	ZT-05-5V	Model	Karl 1.0 Start/Stop 120 Jaar Edition 5d	Maintenance mileage	-
Registration date	08/08/2019	Year	2019	Exterior Color	White Solid
Odometer	93 802 km	Engine size	999	interior Color	Grey
Fuel	Petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Manual	CO2	-
Doors	5	Gears	5		

Inspection Details

Inspection date	21/05/2025	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



Generic equipment

Manual air-conditioning	✓
Cruise control	✓
GPS system	✓
Central locking	✓
Electric windows	✓
Audio System	✓

Removable element

Spare wheel kit	✓
Rear parcel shelf	✓


Technical Document

User manual	✓
Warranty booklet	✓
Spare key	✓
Remote key	✓
Sat Nav CD ROM Software	✓

Tyres

Winter kit

Continental 165/65/14 Winter 7.0 mm



Continental 165/65/14 Winter 7.0 mm



Dunlop 165/65/14 Winter 6.0 mm

Dunlop 165/65/14 Winter 6.0 mm

Exterior

1



●●

Part	Door
Position	Front left
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Smart Repair

2



●●●

Part	Bumper
Position	Back
Damages	Dent & Chips
Severity	Diameter (mm) > 20
Repair mode	Repair

3



●●

Part	Sill
Position	Right
Damages	Dent & Chips
Severity	Diameter (mm) > 20
Repair mode	Repair

4



●●

Part	Door
Position	Front right
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Smart Repair

5



●●

Part	Bumper
Position	Front
Damages	Scratched
Severity	Length (cm) > 10
Repair mode	Repair

Interior damage

6



Part	Interior cleaning
Position	Front left
Damages	Stained/dirty
Severity	-
Repair mode	Cleaning

7



Part	Interior cleaning
Position	Centre
Damages	Stained/dirty
Severity	-
Repair mode	Cleaning