

Damage Review



Jobnr	138844
Fleet	BCA
Lease	
Driver	Bestuurder
Location	
Date	19-09-2025
Date Hour	15:22

Make	OPEL
Model	COMBO
Type	
Licenseplate	2DME997
Chassisnr	W0VEFYHT2NN565285
Color	Wit
First Registration	25-04-2023
Mileage	182808
VP/VU	VP
Fuel	diesel
Fuel Level	1/8
Total Keys	1
Seats MVP	5

Check			
COC	Yes	Safety Kit	No
Registration doc	Yes	Triangle	No
Insurance doc	No	GPS	No
Manual	No	Fuel Card	No
Service book	Yes	Alarm	No
Fire extinguisher	No	Service Needed	Yes
Rear Shelf	No		

Remarks

19 schadelijnen
Inspectie onder voorbehoud
Onderliggende schade
Service nodig
Melding esp

<u>Financial Result Damage Appraisal</u>		
	Acceptable Total	0,00 €
	Not Acceptable Total	0,00 €
	Depreciation	0 %
	Not Acceptable Depreciated Total	0,00 €
	Total Damages	0,00 €
	Total Damages (Depreciation incl.)	0,00 €
		(bedragen excl. BTW)

Signatures

Damage advisor

Client
BCA



exterior	26 WheelRL	WHEELCOVER RL	NA	missing	Replace	€ 0
interior	29 Cleaning	CLEANING	NA	dirty	Cleaning	€ 0
interior	28 Desodorisation		NA	bad smell	Deodorising	€ 0
exterior	1 BumperF	BUMPERPART NOT PAINTED	NA	scratch	Replace	€ 0
exterior	1 BumperF	BUMPER FRONT	NA	scratch	Paint	€ 0
exterior	7 MirrorL	CAP UNPAINTED	NA	scratch	Replace	€ 0
exterior	25 WheelFL	STEEL WHEEL	NA	dent	SR - Rims	€ 0
exterior	11 WingRL	WING RL	NA	scratch + dent	Replace + paint	€ 0
exterior	11 WingRL	COVER WING RL	NA	missing	Replace	€ 0
exterior	11 WingRL	FUEL COVER	NA	missing	Replace	€ 0
exterior	26 WheelRL	STEEL WHEEL	NA	cracked	Replace	€ 0
exterior	11 WingRL	MUDPIT	NA	cracked	Replace	€ 0
exterior	12 LightRL	LIGHT	NA	cracked	Replace	€ 0
exterior	13 BumperR	BUMPER REAR	NA	cracked	Replace	€ 0
exterior	13 BumperR	MOLDING LEFT	NA	cracked	Replace	€ 0
exterior	15 BonnetR	LOADING DOOR RL	NA	scratch + dent	Replace + paint	€ 0
exterior	21 DoorFR	DOOR FR	NA	dent	SR - PDR	€ 0
interior	30 Missing	2ND KEY	NA	missing	Replace	€ 0
exterior	16 Roof	ROOF	A	dent	Repair + paint	€ 0

General Pictures





Damage Appraisal



exterior	26 WheelRL	WHEELCOVER RL	NA missing	Replace	€ 0
----------	------------	---------------	------------	---------	-----

D2



interior	29 Cleaning	CLEANING	NA dirty	Cleaning	€ 0
----------	-------------	----------	----------	----------	-----



interior	28 Desodorisation		NA bad smell	Deodorising	€ 0
----------	-------------------	--	--------------	-------------	-----

exterior	1 BumperF	BUMPERPART NOT PAINTED	NA scratch	Replace	€ 0
----------	-----------	------------------------	------------	---------	-----

D1



exterior	1 BumperF	BUMPER FRONT	NA scratch	Paint	€ 0
----------	-----------	--------------	------------	-------	-----

D1



exterior	7 MirrorL	CAP UNPAINTED	NA scratch	Replace	€ 0
----------	-----------	---------------	------------	---------	-----



exterior	25 WheelFL	STEEL WHEEL	NA dent	SR - Rims	€ 0
----------	------------	-------------	---------	-----------	-----



exterior	11 WingRL	WING RL	NA scratch + dent	Replace + paint	€ 0
----------	-----------	---------	-------------------	-----------------	-----

D2



exterior	11 WingRL	COVER WING RL	NA missing	Replace	€ 0
----------	-----------	---------------	------------	---------	-----

D2



exterior	11 WingRL	FUEL COVER	NA missing	Replace	€ 0
----------	-----------	------------	------------	---------	-----

D2



exterior	26 WheelRL	STEEL WHEEL	NA cracked	Replace	€ 0
----------	------------	-------------	------------	---------	-----



exterior	11 WingRL	MUDPIT	NA cracked	Replace	€ 0
----------	-----------	--------	------------	---------	-----

D2



exterior	12 LightRL	LIGHT	NA cracked	Replace	€ 0
----------	------------	-------	------------	---------	-----

D2



exterior	13 BumperR	BUMPER REAR	NA cracked	Replace	€ 0
----------	------------	-------------	------------	---------	-----

D2



exterior	13 BumperR	MOLDING LEFT	NA cracked	Replace	€ 0
----------	------------	--------------	------------	---------	-----

D2



exterior	15 BonnetR	LOADING DOOR RL	NA scratch + dent	Replace + paint	€ 0
----------	------------	-----------------	-------------------	-----------------	-----

D2



exterior	21 DoorFR	DOOR FR	NA dent	SR - PDR	€ 0
----------	-----------	---------	---------	----------	-----



interior	30 Missing	2ND KEY	NA missing	Replace	€ 0
----------	------------	---------	------------	---------	-----

exterior	16 Roof	ROOF	A dent	Repair + paint	€ 0
----------	---------	------	--------	----------------	-----



Vehicle Condition	Interior: dirty
	Exterior: dirty

Tyres			
Type	Summer	Flat/RSC	No
Spare Tyre	Yes	Repair Kit	No
Front Left			
Profile	5	Side Damage	No
Front Right			
Profile	5	Side Damage	No
Rear Left			
Profile	5	Side Damage	No
Rear Right			
Profile	5	Side Damage	No