



Opel Ampera: H516KZ

Vinnumber:	W0VF86E03K4139894	Versionname:	Ampera-E (voorraad) 150kW/60kWh Business Executive (NEDC)
First Registrationdate:	28/02/2020	Fiscalpower:	
Expertise Mileage:	134025	Power Kw:	150
Bodytype:		Body colour:	Mineral Black Metallic
Gearbox:	Automatic	Paint type:	Metallic
Transmission:	Front	Type of rims (mounted):	Aluminium
Fueltype:	Electric	Parking lot:	742
Number of seats:	5		
Type of rims (mounted):	Aluminium		
Maintenance needed:	Yes		

Options

Number of keys total	2	Telephone equipment
Autom climate control		Lining leather
Windows electric F		Central consol F
Radio multimedia		Luggage cover
		Headlights Xenon/LED/Laser
		Front parking sensors
		Rear parking sensors

Degree of wear

	215/50/17/95 H			
Winter tyres:	Fr.L.	Michelin: 5,5 mm	Fr.R.	Michelin: 3,3 mm
	Re.L.	Michelin: 2,9 mm	Re.R.	Michelin: 3 mm
Tyre profile depth FL				5.5
Tyre profile depth FR				3.3
Tyre profile depth RL				2.9
Tyre profile depth RR				3.0
Tyre size FL				215/50 R 17 95 H
Tyre size FR				215/50 R 17 95 H
Tyre size RL				215/50 R 17 95 H
Tyre size RR				215/50 R 17 95 H
Tyre type FL				Winter
Tyre type FR				Winter
Tyre type RL				Winter
Tyre type RR				Winter
Tyre make FL				261
Tyre make FR				261
Tyre make RL				261
Tyre make RR				261

Assistance equipment

Number of charging cables (normal)	1
Number of charging cables (rapid charge)	1

Service, Maintenance, Execute



Roof liner, Stain, Cleaning



Floor mat(s), Worn, Replace



Door RL, Scratch(es), Repair and paint (complete)



Outside rear-view mirror housing L, Scratch(es), Replace and paint



Door FL, Scratch(es), Polish



Bonnet, Dent(s), Repair and paint (complete)



Bumper F, Scratch(es), Polish



Door RR, Scratch(es), Repair and paint (complete)



Outside rear-view mirror housing R, Scratch(es), Polish



Boot lid covering R, Scratch(es), Replace



Rear window, Scratch(es), Replace



Bumper R, Scratch(es), Repair and paint (complete)



Roof, Dent(s), Repair and paint (complete)

