DEKRA

DEKRA Automotive Solutions

Appraisal Report

DEKRA

Vehicle details

VIN	W0VMRLS09 JB160895	Brand	OPEL	Maintenance date	-
Licence Plate	V8-64-SR	Model	MOVANO L2H2 2.3CDTI 125kW EU6 Tecshift 3.5T 4d	Maintenance mileage	-
Registration date	31/10/2018	Year	2018	Exterior Color	White Solid
Odometer	127 172 km	Engine size	2299	interior Color	Grey
Fuel	Diesel	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Automatic	CO2	-
Doors	4	Gears	-		

Inspection Details

Inspection date	03/10/2025	Inspection loc.	Dekra Ayvens

Generic equipment

Manual air-conditioning	✔
Cruise control	✔
Automatic Gearbox	✔
Tow	✔
Central locking	✔
Electric windows	✔
Park Distance Control	✔
Audio System	✔

Removable element

Spare wheel (wheel & tyre)	✔

Technical Document

User manual	✔
Warranty booklet	✔
Spare key	✔
Remote key	✔

Tyres

Winter kit

Michelin 225/65/16 Winter 6.0 mm

Vredestein 225/65/16 Winter 9.5 mm



Michelin 225/65/16 Winter 4.5 mm

Vredestein 225/65/16 Winter 8.5 mm

Exterior

2

Part	Sill
Position	Right
Damages	Dent & Chips
Severity	-
Repair mode	Repair

3

Part	Bumper
Position	Front
Damages	Scratched
Severity	-
Repair mode	Repair

4

Part	Sill
Position	Left
Damages	Scratched
Severity	-
Repair mode	Repair

5

Part	Step plate
Position	Front left
Damages	Scratched
Severity	-
Repair mode	For info

7

Part	Roof
Position	-
Damages	Dent & Chips
Severity	-
Repair mode	Repair

Interior damage

1

Part	Other interior
Position	-
Damages	Chemical deposit
Severity	-
Repair mode	For info

buitenzijde voertuig

6

Part	Fabric seat
Position	Front left
Damages	Worn out
Severity	-
Repair mode	For info