


Vehicle details

VIN	W0VZRHNSX L6039207	Brand	OPEL	Maintenance date	-
Licence Plate	J5-13-HJ	Model	Grandland X 1.2 Turbo S;S 96kW Innovation 5d	Maintenance mileage	-
Registration date	31/07/2020	Year	2020	Exterior Color	White Solid
Odometer	83 810 km	Engine size	1199	interior Color	Black
Fuel	Petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Manual	CO2	-
Doors	5	Gears	6		

Inspection Details

Inspection date	06/08/2025	Inspection loc.	Ayvens Veghel		
-----------------	------------	-----------------	---------------	--	--



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
GPS system	✓
Alloy wheel rims	✓
Central locking	✓
Electric windows	✓
Mixed upholstery	✓
Park Distance Control	✓
Audio System	✓
Led lighting	✓

Removable element

Spare wheel kit	✓
Rear parcel shelf	✓

Technical Document

User manual	✓
Warranty booklet	✓
Spare key	✓
Remote key	✓
Sat Nav CD ROM Software	✓

Tyres

Michelin 225/55/18 Summer 6.5 mm		Michelin 225/55/18 Summer 6.5 mm	
Michelin 225/55/18 Summer 6.0 mm		Michelin 225/55/18 Summer 4.5 mm	

Exterior

2



Part

Step plate

Position

Back left

Damages

Dent & Chips

Severity

-

Repair mode

For info

●

●

4



Part

Wing moulding

Position

Back right

Damages

Scratched

Severity

-

Repair mode

Repair

●

●

6



Part

Door

Position

Front right

Damages

Scratched

Severity

Length (cm) > 10

Repair mode

Repair

●

●

8



Part

Roof

Position

Inside

Damages

Hail damaged

Severity

Diameter (mm) > 20

Repair mode

Smart Repair

●

●

●

3



Part

Alloy wheel 17"

Position

Back left

Damages

Scratched

Severity

-

Repair mode


For info

●

●

●

5



Part

Door

Position

Back right

Damages

Dented

Severity

Diameter (mm) > 20

Repair mode

Smart Repair

●

●

●

7



Part

Step plate

Position

Back right

Damages

Dent & Chips

Severity

-

Repair mode


For info

●

●

●

9



Part

Bonnet

Position

-

Damages

Dented

Severity

Diameter (mm) > 20

Repair mode


Smart Repair

●

●

Interior damage

1



Part	Interior cleaning
Position	Front left
Damages	Stained/dirty
Severity	-
Repair mode	Cleaning