


Vehicle details

VIN	W0VZT6EB0 L1007658	Brand	OPEL	Maintenance date	-
Licence Plate	G2-71-NB	Model	Insignia Grand Sport 1.5 Turbo 121kW S;S Bus. Exec	Maintenance mileage	-
Registration date	31/10/2019	Year	2019	Exterior Color	Grey Metallic
Odometer	172 452 km	Engine size	1490	interior Color	Black
Fuel	Petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Automatic	CO2	-
Doors	5	Gears	-		

Inspection Details

Inspection date	15/05/2025	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
GPS system	✓
Sliding roof	✓
Alloy wheel rims	✓
Automatic Gearbox	✓
Metallic paint	✓
Central locking	✓
Electric windows	✓
Mixed upholstery	✓
Park Distance Control	✓
Audio System	✓
Led lighting	✓

Removable element

Spare wheel (wheel & tyre)	✓
Rear parcel shelf	✓


Technical Document

User manual	✓
Warranty booklet	✓
Spare key	✓
Remote key	✓
Sat Nav CD ROM Software	✓

Tyres

Winter kit

Bridgestone 215/55/17 Winter 6.0 mm



Bridgestone 215/55/17 Winter 6.0 mm



Michelin 215/55/17 Winter 5.0 mm

Michelin 215/55/17 Winter 6.0 mm

Exterior

1



Part

Alloy wheel 17"

Position

Front left

Damages

Scratched

Severity

-

Repair mode

Lumpsum repair

●

●

●

2



Part

Roof wind deflector

Position

-

Damages

Dent & Chips

Severity

Diameter (mm) > 20

Repair mode

Repair

●

●

4



Part

Alloy wheel 17"

Position

Back right

Damages

Scratched

Severity

-

Repair mode

Lumpsum repair

●

●

6



Part

Bumper

Position

Front

Damages

Scratched

Severity

Length (cm) > 10

Repair mode

Repair

●

●

●

●

7



Part

Bonnet

Position

-

Damages

Chemical deposit

Severity

-

Repair mode

Lumpsum repair

●

●

●

●

●

8



Part

Roof

Position

-

Damages

Chemical deposit

Severity

-

Repair mode

Lumpsum repair

●

●

●

Interior damage

3



Part	Interior tailgate lining
Position	-
Damages	Scratched
Severity	-
Repair mode	Smart Repair

5



Part	C-pillar trim
Position	Front right
Damages	Scratched
Severity	-
Repair mode	Smart Repair