



## Opel Insignia: H349BV

|                         |                   |                         |                                                            |
|-------------------------|-------------------|-------------------------|------------------------------------------------------------|
| Vinnumber:              | W0VZT6EB5L1007641 | Versionname:            | Insignia Grand Sport 1.5 Turbo 121kW S&S Business Exe. aut |
| First Registrationdate: | 3/01/2020         | Fiscalpower:            |                                                            |
| Expertise Mileage:      | 181291            | Power Kw:               | 121                                                        |
| Bodytype:               |                   | Body colour:            | Abalone White (P)                                          |
| Gearbox:                | Automatic         | Paint type:             | Metallic                                                   |
| Transmission:           | Front             | Type of rims (mounted): | Aluminium                                                  |
| Fueltype:               | Petrol            | Parking lot:            | awl                                                        |
| Number of seats:        | 5                 |                         |                                                            |
| Type of rims (mounted): | Aluminium         |                         |                                                            |
| Maintenance needed:     | Yes               |                         |                                                            |

## Options

|                        |   |                            |
|------------------------|---|----------------------------|
| Number of keys total   | 1 | Telephone equipment        |
| GPS                    |   | Lining semi-leather        |
| Autom climate control  |   | Central consol F           |
| Windows electric F     |   | Luggage cover              |
| Radio multimedia       |   | Headlights Xenon/LED/Laser |
| Keys removable towhook |   | Front parking sensors      |
|                        |   | Rear parking sensors       |
|                        |   | Tow bar removable          |

## Degree of wear

| 245/45/18/96 V        |       |                     |       |                     |
|-----------------------|-------|---------------------|-------|---------------------|
| Winter tyres:         | Fr.L. | Continental: 3 mm   | Fr.R. | Continental: 3 mm   |
|                       | Re.L. | Bridgestone: 5,2 mm | Re.R. | Bridgestone: 4,4 mm |
| Tyre profile depth FL |       |                     |       | 3.0                 |
| Tyre profile depth FR |       |                     |       | 3.0                 |
| Tyre profile depth RL |       |                     |       | 5.2                 |
| Tyre profile depth RR |       |                     |       | 4.4                 |
| Tyre size FL          |       |                     |       | 245/45 R 18 096 V   |
| Tyre size FR          |       |                     |       | 245/45 R 18 096 V   |
| Tyre size RL          |       |                     |       | 245/45 R 18 100 V   |
| Tyre size RR          |       |                     |       | 245/45 R 18 100 V   |
| Tyre type FL          |       |                     |       | Winter              |
| Tyre type FR          |       |                     |       | Winter              |
| Tyre type RL          |       |                     |       | Winter              |
| Tyre type RR          |       |                     |       | Winter              |
| Tyre make FL          |       |                     |       | 256                 |
| Tyre make FR          |       |                     |       | 256                 |
| Tyre make RL          |       |                     |       | 255                 |
| Tyre make RR          |       |                     |       | 255                 |

## Assistance equipment

|                                          |   |
|------------------------------------------|---|
| Number of charging cables (normal)       | 0 |
| Number of charging cables (rapid charge) | 0 |

Service, Maintenance, Execute



Ignition key, Missing, Replace

No pictures to display

Interior covering A pillar L, Stain, Cleaning



Interior, Dirty, Cleaning



Door RL, Scratch(es), Repair and paint (complete)



Bumper F, Scratch(es), Repair and paint (complete)



Bumper R, Scratch(es), Repair and paint (complete)



Steering wheel, Worn, Replace

