


Vehicle details

VIN	W0VZT6GBX L1029356	Brand	OPEL	Maintenance date	-
Licence Plate	J0-20-NT	Model	Insignia Grand Sport 1.5 Turbo 121kW S&S Bus.	Maintenance mileage	-
Registration date	23/09/2020	Year	2020	Exterior Color	Black Metallic
Odometer	94 199 km	Engine size	1490	interior Color	Black
Fuel	Petrol	Body Type	-	Next technical inspection	-
Seats	5	Transmission	Automatic	CO2	-
Doors	5	Gears	-		

Inspection Details

Inspection date	16/09/2025	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
Leather	✓
GPS system	✓
Alloy wheel rims	✓
Automatic Gearbox	✓
Heating seats	✓
Electric seats	✓
Tow	✓
Metallic paint	✓
Central locking	✓
Electric windows	✓
Park Distance Control	✓
Audio System	✓

Removable element

Spare wheel kit	✓
Rear parcel shelf	✓

Technical Document

User manual	✓
Warranty booklet	✓
Spare key	✓
Remote key	✓
Sat Nav CD ROM Software	✓

Tyres

Continental 245/35/20 Summer 4.5 mm		Continental 245/35/20 Summer 5.0 mm	
Pirelli 245/35/20 Summer 7.0 mm		Pirelli 245/35/20 Summer 7.0 mm	

Exterior

1		Part Position Damages Severity Repair mode	Roof - Dented Diameter (mm) > 20 Smart Repair	2		Part Position Damages Severity Repair mode	Bumper Front Scratched Length (cm) > 10 Repair
	● ●				● ● ● ● ●		
3		Part Position Damages Severity Repair mode	Alloy wheel 20" Front right Scratched - Lumpsum repair	4		Part Position Damages Severity Repair mode	Door Back right Dented Diameter (mm) > 20 Smart Repair
	● ●				● ●		
5		Part Position Damages Severity Repair mode	Wing Back right Dented Diameter (mm) > 20 Smart Repair	6		Part Position Damages Severity Repair mode	Alloy wheel 20" Back right Scratched - Lumpsum repair
	● ●				● ●		
7		Part Position Damages Severity Repair mode	Bumper Back Scratched Length (cm) > 10 Repair	8		Part Position Damages Severity Repair mode	Alloy wheel 20" Back left Scratched - Lumpsum repair
	● ● ●				● ●		
9		Part Position Damages Severity Repair mode	Door Back left Dented Diameter (mm) > 20 Smart Repair	10		Part Position Damages Severity Repair mode	Alloy wheel 20" Front left Scratched - Lumpsum repair
	● ●				● ●		