

Vehicle details

VIN	W0VZX6GH1 K1035781	Brand	OPEL	Maintenance date	-
Licence Plate	51-DM-R7	Model	Insignia Grand Sport 2.0 BiTurbo diesel GSi auto 4	Maintenance mileage	-
Registration date	01/02/2019	Year	2019	Exterior Color	White Solid
Odometer	204 776 km	Engine size	1956	interior Color	Black
Fuel	Diesel	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Automatic	CO2	-
Doors	5	Gears	-		

Inspection Details

Inspection date	25/04/2025	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
Leather	✓
GPS system	✓
Alloy wheel rims	✓
Automatic Gearbox	✓
Heating seats	✓
Electric seats	✓
Metallic paint	✓
Central locking	✓
Electric windows	✓
Park Distance Control	✓
Audio System	✓
Led lighting	✓

Removable element

Rear parcel shelf	✓
-------------------	---


Technical Document

User manual	✓
Warranty booklet	✓
Spare key	✓
Remote key	✓
Sat Nav CD ROM Software	✓

Tyres

Winter kit

Continental 235/45/18 Winter 5.0 mm



Continental 235/45/18 Winter 5.0 mm



Continental 235/45/18 Winter 6.5 mm

Continental 235/45/18 Winter 6.5 mm

Exterior

1



Part	Alloy wheel 18"
Position	Front left
Damages	Scratched
Severity	-
Repair mode	Lumpsum repair

2



Part	Door
Position	Back left
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Smart Repair

3



Part	Wing
Position	Back left
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Smart Repair

4



Part	Bumper
Position	Back
Damages	Dent & Chips
Severity	Diameter (mm) > 20
Repair mode	Repair

5



Part	Alloy wheel 18"
Position	Back left
Damages	Scratched
Severity	-
Repair mode	Lumpsum repair

6



Part	Alloy wheel 18"
Position	Back right
Damages	Scratched
Severity	-
Repair mode	Lumpsum repair

7



Part	Wing
Position	Back right
Damages	Dent & Chips
Severity	Diameter (mm) > 20
Repair mode	Repair

8



Part	Door
Position	Back right
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Smart Repair

9



Part	Alloy wheel 18"
Position	Front right
Damages	Scratched
Severity	-
Repair mode	Lumpsum repair

10



Part	Bumper
Position	Front
Damages	Scratched
Severity	Length (cm) > 10
Repair mode	Repair

11



Part	Roof
Position	-
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Smart Repair