



Mercedes CLA-Klasse (KKL): 2AXU788

Vinnumber:	W1K1183121N248162	Versionname:	CLA200d Sedan Business Solution 2.0d 150pk/cv 4p 8G-DCT
First Registrationdate:	1/09/2021	Fiscalpower:	
Expertise Mileage:	102218	Power Kw:	110
Bodytype:		Type of rims (mounted)	Aluminium
Gearbox:	Automatic		
Transmission:			
Fueltype:			
Maintenance	OK		
Maintenance	14675.0		
Battery functioning	Yes		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Type of Tow bar	No Tow bar
GPS			
Type of Maintenance book	Digital maintenance		
Type of GPS storage	HD		

Tyres

225/45/18/95 Y				
Summer tyres:	Fr.L.	Fulda: 4 mm	Fr.R.	Fulda: 4 mm
	Re.L.	Continental: 5 mm	Re.R.	Continental: 5 mm
Tyre profile depth FL				4.0
Tyre profile depth FR				4.0
Tyre profile depth RL				5.0
Tyre profile depth RR				5.0
Tyre size FL				225/45 R 18 95 Y
Tyre size FR				225/45 R 18 95 Y
Tyre size RL				225/45 R 18 91 V
Tyre size RR				225/45 R 18 91 W
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				2484
Tyre make FR				2484
Tyre make RL				256
Tyre make RR				256

Assistance equipment

Number of charging cables (normal)	0
Number of charging cables (rapid charge)	0

Bumper F, Scratch(es), Repair and paint (complete)





Bonnet, Stone chip(s), Acceptable



Bumper moulding F, Deformed / Strained, Acceptable



Alloy rim FL polished, Chemical polution, Repair and paint (complete)



Alloy rim RL polished, Scratch(es), Repair and paint (complete)



Central pillar L, Dent(s) and scratch(es), Acceptable



Door RL, Dent(s), Acceptable



Tyre repair kit, Missing, Check



Bumper R, Scratch(es), Polish



Alloy rim RR polished, Scratch(es), Repair and paint (complete)



Outside rear-view mirror housing R, Scratch(es), Acceptable



Wing FR, Scratch(es), Polish

