



Mercedes CLA-Klasse (KKL): 2BCZ508

Vinnumber:	W1K1183121N258779	Versionname:	CLA200d Sedan Business Solution 2.0d 150pk/cv 4p 8G-DCT
First Registrationdate:	6/10/2021	Fiscalpower:	
Expertise Mileage:	41349	Power Kw:	110
Bodytype:		Type of rims (mounted)	Aluminium
Gearbox:	Automatic		
Transmission:			
Fueltype:			
Maintenance	OK		
Maintenance	Over 62 dagen		
Battery functioning	Yes		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Type of Tow bar	No Tow bar
GPS			
Type of Maintenance book	Digital maintenance		
Type of GPS storage	HD		

Tyres

	225/45/18/91 W			
Summer tyres:	Fr.L.	Bridgestone: 6 mm	Fr.R.	Bridgestone: 6 mm
	Re.L.	Continental: 6 mm	Re.R.	Continental: 6 mm
Tyre profile depth FL				6.0
Tyre profile depth FR				6.0
Tyre profile depth RL				6.0
Tyre profile depth RR				6.0
Tyre size FL				225/45 R 18 91 W
Tyre size FR				225/45 R 18 91 W
Tyre size RL				225/45 R 18 91 W
Tyre size RR				225/45 R 18 91 W
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				255
Tyre make FR				255
Tyre make RL				256
Tyre make RR				256

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Backrest cover FL, Damaged, Acceptable



Bumper F, Scratch(es), Spot repair



Door FL, Scratch(es), Acceptable



Tailgate / Boot, Scratch(es), Acceptable



Bumper moulding R, Scratch(es), Acceptable



Alloy rim RR polished, Scratch(es), Acceptable



Door FR, Dent(s), Paintless dent repair



Outside rear-view mirror cover R (upper), Scratch(es), Acceptable



Alloy rim FR polished, Scratch(es), Repair and paint (complete)



Central pillar R, Dent(s) and scratch(es), Repair and paint (complete)



Door FR, Dent(s), Repair and paint (complete)

