



MERCEDES CLA: 1YTP456			
Vinnumber:	W1K1183871N187798	Versionname:	CLA 200 Business Solution
First Registrationdate:	9/12/2020	Fiscalpower:	
Expertise Mileage:	23883	Power Kw:	120
Bodytype:		Body colour	White
Gearbox:	Automatic	Type of rims (mounted)	Aluminium
Transmission:		Parking lot	1312
Fueltype:	Petrol		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		
Options			
Number of keys total	2	Seats electric F L	
Cruise Control		Seats electric F R	
Steering wheel multifunctional		Panoramic roof	
Seats F heated		Front parking sensors	
Radio multimedia		Rear parking sensors	
Type of headlighting	Headlighting LED	Type of Tow bar	Tow bar collapsible
Type of GPS	GPS big screen color		
Type of Lining	Lining artificial leather and alcantara		
Type of climate control	Autom climate control		
Limited Technical Inspection			
Tyres			
Summer tyres:	225/45/18/92 H		
	Fr.L.	Continental: 5 mm	Fr.R. Continental: 5 mm
	Re.L.	Continental: 5 mm	Re.R. Continental: 5 mm
Tyre profile depth FL	5.0		
Tyre profile depth FR	5.0		
Tyre profile depth RL	5.0		
Tyre profile depth RR	5.0		
Tyre size FL	225/45 R 18 92 H		
Tyre size FR	225/45 R 18 92 H		
Tyre size RL	225/45 R 18 92 H		
Tyre size RR	225/45 R 18 92 H		
Tyre type FL	Summer		
Tyre type FR	Summer		
Tyre type RL	Summer		
Tyre type RR	Summer		
Tyre make FL	256		
Tyre make FR	256		
Tyre make RL	256		
Tyre make RR	256		
Assistance equipment			
Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		
Total cost ex VAT		1570,90	
Interior, Dirty, Cleaning		170,61	



Interior, Smell, Ozone treatment	208,23
----------------------------------	--------



Bonnet, Chemical polution, Repair and paint (complete)	395,90
--	--------



Bumper F, Bad repair, Check	0,00
-----------------------------	------



Alloy rim RL polished, Scratch(es), Repair and paint (complete)	199,04
---	--------



Alloy rim FL polished, Scratch(es), Repair and paint (complete)	199,04
---	--------



Wing FL, Bad repair, Check	0,00
----------------------------	------



Alloy rim FR polished, Scratch(es), Repair and paint (complete)	199,04
---	--------



Alloy rim RR polished, Scratch(es), Repair and paint (complete)	199,04
---	--------



Wing RR, Dent(s), Acceptable	0,00
------------------------------	------

