

INSPECTION REPORT


End of contract

GENERAL INFO

File	303023
License plate	1YWR127
Vehicle identification number	W1K1186121N188285
Dossier	2020163103
Make	Mercedes CLA SB 200 d Bus.Solu
Mileage	138638
First registration	13/01/2021
client availability date	16/01/2026
inspectionDate	28/01/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
12	Bumper Front // Smart Repair Large	N
18	Bumper Front / Spoiler / Replace	N
72	Side View Mirror Left // Painting	Y
81	Door Front Left // Smart Repair Medium	N
91	Rocker Panel Left // Smart Repair Medium	N
100	Door Rear Left // Smart Repair Small	Y
156	Rear Bonnet // Polish	Y
159	Rear Bonnet / Rear Window / Replace	Y
174	Light / Rear Right / Replace	Y
186	Wing Rear Right // Polish	Y
196	Door Rear Right // Polish	Y
201	Rocker Panel Right // Smart Repair Medium	Y
214	Door Front Right // Repair & Painting	Y
222	Side View Mirror Right // Painting	Y
236	Wing Front right // Polish	Y
310	Wheel Two Tone Front Left // Repair	N
330	Wheel Two Tone Rear Right // Repair	N
340	Wheel Two Tone Front Right // Repair	N
413	Seat Front Left / Rear Coating / Replace	Y
539	Trunk Compartment / Back Coating / Replace	Y

Damage Pictures





Damage within Renta-norm-



Wheel Two Tone Front Right // Repair-scratch



Wing Front right // Polish-scratch



Side View Mirror Right // Painting-scratch



Door Rear Left // Smart Repair Small-dent



Rocker Panel Right // Smart Repair Medium-scratch + dent



Door Front Right // Repair & Painting-scratch + dent



Seat Front Left / Rear Coating / Replace-tear



Trunk Compartment / Back Coating / Replace-hole



Door Rear Right // Polish-scratch



Wing Rear Right // Polish-scratch



Wheel Two Tone Rear Right // Repair-scratch




Light / Rear Right / Replace-scratch



Rear Bonnet // Polish-scratch






Rear Bonnet / Rear Window / Replace-scratch



Rocker Panel Left // Smart Repair Medium-scratch



Door Front Left // Smart Repair Medium-scratch



Side View Mirror Left // Painting-scratch



Wheel Two Tone Front Left // Repair-scratch



Bumper Front // Smart Repair Large-scratch



Bumper Front / Spoiler / Replace-scratch